Profile/Photo Observation Report



Date: **04/04/2018** Weather: Coding: **PACP 6.0**

Pipe Length (ft): 279.2 Owner: NA Pre Clean: No Pre-Cleaning P.O.#: Surveyor: Jen Costello PSR: P-607-026-023

Customer: Clean Date: 01/01/1900 Shape: C

Street: POLLY LN Flow Control: Not Controlled

City: Hobart, IN Year Renewed: Location: Yard Tape/Media #:

Purpose: Routine Assessment Dia/Height: 8"
Use: Sanitary Material: PVC

Drain Area: **NA** Lining:

Category: NA
Comment: Flow direction is marked wrong.


Location Details: Direction of Survey: Upstream

US MH: M-607-023 DS MH: M-607-026 Total Length Surveyed (ft): 280.2

2.00 2400 8.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 2.00 2400 8.00 Overall Index: Overall Quick: Overall Rating:


	Position	Code	Observation	Video (sec)	Grade
607	026				
	0.	AMH	Manhole	10	NA
	0.	DAGS(S01)	Deposits Attached Grease	21	M 2
	\ <u>\</u> \\.0	MWL	Water Level	32	NA
	22.5	TF	Tap Factory	91	NA
	22.5	DAGS(F01)	Deposits Attached Grease	104	M 2
ш	24.6	TF	Tap Factory	120	NA
ш	121.6	TF	Tap Factory	326	NA
	124.2	TFA	Tap Factory Active	343	NA
	//224.4	TF	Tap Factory	555	NA
	227.0	TFA	Tap Factory Active	573	NA
	280.2	AMH	Manhole	691	NA

Code:



Description:	Manhole
Distance (ft): Structural Grade:	.0 0
O&M Grade: Clock Start/From:	0
Clock To: 1st Value:	
2nd Value:	
Value Percent: Continuous Index:	
Within 8" of Joint: Remarks:	NO M-607-026

AMH



Code: DAGS

Description: Deposits Attached Grease

Distance (ft): .0
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 7
Clock To: 5
1st Value:

2nd Value:

Value Percent: 5.000
Continuous Index: S01
Within 8" of Joint: NO

Remarks:

Code: MWL
Description: Water Level



Distance (ft): .0

Structural Grade: **0**O&M Grade: **0**


Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO



Code: **TF**

Description: Tap Factory

Distance (ft): 22.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value:

4.000

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:




Code: DAGS

Description: Deposits Attached Grease

Distance (ft): 22.5
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 7
Clock To: 5
1st Value:
2nd Value:

Value Percent: 5.000
Continuous Index: F01
Within 8" of Joint: NO



Code: **TF**

Description: Tap Factory

Distance (ft): 24.6
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 11

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Description: Tap Factory




Distance (ft): 121.6
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: TFA

Description: Tap Factory Active


Distance (ft): 124.2
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 11

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**

Description: Tap Factory

Distance (ft): 224.4
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: TFA

Description: Tap Factory Active

Distance (ft): 227.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: AMH
Description: Manhole

Distance (ft): 280.2
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-607-023