## **Profile/Photo Observation Report**



Date: 04/04/2018 Weather: **PACP 6.0** Coding:

Pipe Length (ft): 283.8 Owner: NA Pre Clean: No Pre-Cleaning P.O.#: Jen Costello PSR: P-607-028-027

Customer: Clean Date: 01/01/1900 Shape:

**POLLY LN** Flow Control: **Not Controlled** Street:

Surveyor:

City: Hobart, IN Year Renewed: Yard Tape/Media #: Location:

Purpose: **Routine Assessment** Dia/Height: 8" **PVC** Use: Sanitary Material:

NΑ Drain Area: Lining:

NA Category: Comment: Flow direction is marked wrong.

**Location Details:** Direction of Survey: **Downstream** 

US MH: M-607-027 Total Length Surveyed (ft): DS MH: M-607-028 274.6

0.00 0000 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 0.00 0000 0.00 Overall Index: Overall Quick: Overall Rating:

	Position	Code	Observation	Video (sec)	Grade
607-	027				
$\smile$	0.	AMH	Manhole	10	NA
ш	0.	MWL	Water Level	21	NA
	26.3	TF	Tap Factory	86	NA
ш	115.4	TFA	Tap Factory Active	276	NA
ш	122.3	TF	Tap Factory	303	NA
	193.5	MWL	Water Level	458	NA
	215.0	TF	Tap Factory	512	NA
	223.7	TFA	Tap Factory Active	542	NA
ш	254.0	TFA	Tap Factory Active	615	NA
ш	267.3	TFA	Tap Factory Active	653	NA
	274.6	AMH	Manhole	680	NA

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-607-027

 $\mathsf{AMH}$ 



Code: MWL

Description: **Water Level** 

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 20.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: TF

Description: **Tap Factory** 

Distance (ft): 26.3 Structural Grade: 0 O&M Grade: 0 Clock Start/From: 9

Clock To:

Remarks:

1st Value: 4.000

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: TFA

Description: Tap Factory Active


Distance (ft): 115.4
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF** 

Description: Tap Factory

Distance (ft): 122.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 9

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: MWL
Description: Water Level

Distance (ft): 193.5
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:


Value Percent: 30.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: **TF** 

Description: Tap Factory


Distance (ft): 215.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: TFA

Description: Tap Factory Active

Distance (ft): 223.7
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 9

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: TFA

Description: Tap Factory Active

Distance (ft): 254.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: TFA

Description: Tap Factory Active

Distance (ft): 267.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 9

Clock To:

1st Value:

4.000

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: AMH
Description: Manhole

Distance (ft): 274.6
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-607-028