Profile/Ph	oto Observation	Report				RedZone
Date:	04/11/2018	Weather:			Coding:	PACP 6.0
Pipe Length (ft	:): 216.4	Owner:	NA		Pre Clean:	No Pre-Cleaning
P.O.#:		Surveyor:	Jen Costello		PSR:	P-607-053-054
Customer:		Clean Date:	01/01/1900		Shape:	с
Street:	MEDLEE DR		Flow Control:		Not Controlled	
City:	Hobart, IN		Year Renewed	:		
Location:	Yard		Tape/Media #:			
Purpose:	Routine Assessmer	nt	Dia/Height:		10"	
Use:	Sanitary		Material:		PVC	
Drain Area:	NA		Lining:			
Category:	NA					
Comment:						
Location Detai	ls:		Direction of Su	rvey:	Upstream	
US MH:	M-607-053	DS MH:	M-607-054	Total Len	ngth Surveyed (ft):	215.2
O&M Index:	2.50	O&M Quick:	31	21 C	D&M Rating:	5.00
Structural Index:	0.00	Structural Qu	ick: 00	200	Structural Rating:	0.00
Overall Index:	2.50	Overall Quick	: 31	. <mark>21 </mark> (Overall Rating:	5.00

	Position	Code	Observation	Video (sec)	Grade
M(607	7-054				
	.0	AMH	Manhole	10	NA
	.0	MWL	Water Level	21	NA
- 11	137.6	TFA	Tap Factory Active	308	NA
- 11	139.1	TFD	Tap Factory Defective	323	M 2
- 11	139.1	DAE	Deposits Attached Encrustation	335	M 3
- 11	175.3	TF	Tap Factory	420	NA
- 11	177.0	TF	Tap Factory	436	NA
- 11	205.6	TF	Tap Factory	505	NA
- 11	207.3	TF	Tap Factory	520	NA
5	215.2	AMH	Manhole	548	NA
D					
Camera Direction					



Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-607-054



Code: MWL Description: Water Level

.0
0
0
20.000
NO



Code: Description:	TFA Tap Factory Active
Distance (ft):	137.6
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	10
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code: Description:	TFD Tap Factory Defective
Distance (ft):	139.1
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	1
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	

dae

DAE


Deposits Attached Encrustation

Within 8" of Joint:


Remarks:

Code:

Description:




Distance (ft):	139.1
Structural Grade:	0
O&M Grade:	3
Clock Start/From:	1
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	15.000
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code:	TF
Description:	Tap Factory
	475.0
Distance (ft):	175.3
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	10
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code: Description:	TF Tap Factory
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint:	177.0 0 2 4.000
Remarks:	



Code:	TF
Description:	Tap Factory

Distance (ft):	205.6
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	10
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code: Description:	TF Tap Factory
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint: Remarks:	207.3 0 0 10 4.000



Code: AMH Description: Manhole

Distance (ft):	215.2
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-607-053