

Profile/Ph	oto Observation	Report			RedZon
Date:	04/11/2018	Weather:		Coding:	PACP 6.0
Pipe Length (ft	z): <b>331.4</b>	Owner:	NA	Pre Clean:	No Pre-Cleaning
P.O.#:		Surveyor:	Jen Costello	PSR:	P-607-054-071
Customer:		Clean Date:	01/01/1900	Shape:	С
Street:	OFF W 10TH ST		Flow Control:	Not Controlled	
City:	Hobart, IN		Year Renewed:		
Location:	Yard		Tape/Media #:		
Purpose:	Routine Assessmen	t	Dia/Height:	10"	
Use:	Sanitary		Material:	PVC	
Drain Area:	NA		Lining:		
Category:	NA				
Comment:					
Location Detai	ls:		Direction of Sur	vey: Upstream	
US MH:	M-607-054	DS MH:	M-607-071	Total Length Surveyed (ft)	): <b>323.9</b>
0&M Index:	0.00	O&M Quick:	000	00 O&M Rating:	0.00
tructural Index	0.00	 Structural Qu	uick: 000	00 Structural Rating:	0.00
Overall Index:	0.00	Overall Quick			0.00






Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-607-071



Code: MWL Description: Water Level

Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	10.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code: Description:	MWL Water Level
Distance (ft):	66.2
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	20.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	

## Thursday, November 16, 2023



Code: MWL Description: Water Level

Distance (ft):	245.0	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:	30.000	
Continuous Index:		
Within 8" of Joint:	NO	
Remarks:		



Code:	АМН	
Description:	Manhole	
Distance (ft):	323.9	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:		
Continuous Index:		
Within 8" of Joint:	NO	
Remarks:	M-607-054	