## **Profile/Photo Observation Report**

0.00

3.00

Structural Index:

Overall Index:

Structural Quick:

Overall Quick:



0.00

3.00

Date:	04/09/2018	Weather:		Coding:	PACP 6.0
Pipe Length (f	t):	Owner:	City of Hobart	Pre Clean:	Not Known
P.O.#:	214	Surveyor:	B. Helbling	PSR:	P-607-060-061
Customer:	City of Hobart	Clean Date:	:	Shape:	С
Street:	West 14th Street		Flow Control:	Not Controll	ed
City:	Hobart, IN		Year Renewed:		
Location:	<b>Light Highway</b>		Tape/Media #:	DEP214	
Purpose:	Routine Assessmen	nt	Dia/Height:	15"	
Use:	Sanitary		Material:	PVC	
Drain Area:			Lining:		
Category:	NA				
Comment:	YES501824 Submital 2				
Location Details:		Direction of Sur	vey: <b>Downstream</b>	ı	
US MH:	M-607-060	DS MH:	M-607-061	Total Length Surveyed	(ft): <b>8.0</b>
0&M Index:	3.00	O&M Quick:	. 31	00 O&M Rating:	3.00

0000


3100

Structural Rating:

Overall Rating:

Position	Code	Observation	Video (sec)	Grade
1(607-)060				
.0	АМН	Manhole	0	NA
0.	MWL	Water Level	18	NA
4.0	DSF	Deposits Settled Fine	228	M 3
5.0	MSA	Abandoned Survey	320	NA
1-607-061				

Code:



Description: Manhole Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint: NO Remarks: M-607-060

**AMH** 



Code: MWL
Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 15.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: **DSF** 

Description: Deposits Settled Fine

Distance (ft): 4.0
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 4
Clock To: 8
1st Value:

2nd Value:

Value Percent: 15.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: MSA

Description: Abandoned Survey

Distance (ft): 5.0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: Rolling on debris/thick sediment