Profile/Photo Observation Report



Date: **04/03/2018** Weather: Coding: **PACP 6.0**

Pipe Length (ft): 76.1 Owner: NA Pre Clean: No Pre-Cleaning P.O.#: Surveyor: Jen Costello PSR: P-607-069-038

Customer: Clean Date: 01/01/1900 Shape: C

Street: MEDLEE DR Flow Control: Not Controlled

City: Hobart, IN Year Renewed: Location: Yard Tape/Media #:

Purpose: Routine Assessment Dia/Height: 8"
Use: Sanitary Material: PVC

Drain Area: **NA** Lining:

Category: NA

Comment:


Location Details: Direction of Survey: **Downstream**

US MH: M-607-069 DS MH: M-607-038 Total Length Surveyed (ft): 70.9

0000 0.00 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 0.00 0000 0.00 Overall Rating: Overall Index: Overall Quick:

Position	Code	Observation	Video (sec)	Grade
M (607- 069				
.0	AMH	Manhole	10	NA
0.	MWL	Water Level	21	NA
55.0	TFA	Tap Factory Active	144	NA
70.9	АМН	Manhole	188	NA
Camera Direction				

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade: O&M Grade:	0
Clock Start/From: Clock To:	
1st Value: 2nd Value:	
Value Percent: Continuous Index:	
Within 8" of Joint: Remarks:	NO M-607-069

AMH



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:


Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

NO

Remarks:



Code: TFA

Description: Tap Factory Active

Distance (ft): 55.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 9

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: AMH
Description: Manhole

Distance (ft): 70.9
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-607-038