

| Profile/Ph | oto Observation | Report | | | | RedZone |
|------------------|-------------------|---------------|--------------|---------|---------------------------|-----------------|
| Date: | 04/03/2018 | Weather: | | | Coding: | PACP 6.0 |
| Pipe Length (ft |): 384.4 | Owner: | NA | | Pre Clean: | No Pre-Cleaning |
| P.O.#: | | Surveyor: | Jen Costelle | כ | PSR: | P-607-080-079 |
| Customer: | | Clean Date: | 01/01/190 | כ | Shape: | с |
| Street: | FOXCROFT STREET | | Flow Control | : | Not Controlled | |
| City: | Hobart, IN | | Year Renewe | ed: | | |
| Location: | Yard | | Tape/Media | #: | | |
| Purpose: | Routine Assessmen | nt | Dia/Height: | | 8" | |
| Use: | Sanitary | | Material: | | PVC | |
| Drain Area: | NA | | Lining: | | | |
| Category: | NA | | | | | |
| Comment: | | | | | | |
| Location Detail | ls: | | Direction of | Survey: | Upstream | |
| US MH: | M-607-080 | DS MH: | M-607-079 | Тс | otal Length Surveyed (ft) | 350.8 |
| 0&M Index: | 2.00 | O&M Quick: | | 2A00 | O&M Rating: | 26.00 |
| tructural Index: | 0.00 | Structural Qu | uick: | 0000 | Structural Rating: | 0.00 |
| Overall Index: | 2.00 | Overall Quic | k: | 2A00 | Overall Rating: | 26.00 |

| | Position | Code | Observation | Video (sec) | Grade |
|------------------|----------|-----------|--------------------------|-------------|-------|
| M-60 | 7-079 | | | | |
| | .0 | AMH | Manhole | 10 | NA |
| - 11 | .0 | MWL | Water Level | 21 | NA |
| - 11 | 0. | DAGS(S01) | Deposits Attached Grease | 32 | M 2 |
| - 11 | 61.3 | TF | Tap Factory | 167 | NA |
| - 83 | 64.9 | DAGS(F01) | Deposits Attached Grease | 186 | M 2 |
| | 85.0 | TF | Tap Factory | 237 | NA |
| - 11 | 260.7 | TF | Tap Factory | 601 | NA |
| - 11 | 302.7 | MWL | Water Level | 697 | NA |
| - 11 | 311.5 | TF | Tap Factory | 726 | NA |
| 5 | 326.8 | TF | Tap Factory | 769 | NA |
| i i | 350.8 | MSA | Abandoned Survey | 829 | NA |
| Camera Direction | | | | | |
| | | | | | |



| Code: Description: | AMH Manhole |
|-----------------------|----------------|
| Distance (ft): | .0 |
| Structural Grade: | .0 |
| O&M Grade: | 0 |
| Clock Start/From: | · |
| Clock To: | |
| 1st Value: | |
| 2nd Value: | |
| Value Percent: | |
| Continuous Index: | |
| Within 8" of Joint: | NO |
| Remarks: | M-607-079 |
| | |



Code: Description:

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: 30.000 Continuous Index: Within 8" of Joint: NO Remarks:


MWL

Water Level



| Code: | DAGS |
|--------------|--------------------------|
| Description: | Deposits Attached Grease |

| Distance (ft): | .0 |
|---------------------|-------|
| Structural Grade: | 0 |
| O&M Grade: | 2 |
| Clock Start/From: | 8 |
| Clock To: | 4 |
| 1st Value: | |
| 2nd Value: | |
| Value Percent: | 5.000 |
| Continuous Index: | S01 |
| Within 8" of Joint: | NO |
| Remarks: | |



| Code: | TF |
|-------------------|-------------|
| Description: | Tap Factory |
| | |
| Distance (ft): | C1 2 |
| Distance (ft): | 61.3 |
| Structural Grade: | 0 |
| O&M Grade: | 0 |
| Clock Start/From: | 2 |
| Clock To: | |
| 1st Value: | 4.000 |
| 2nd Value: | |
| Value Percent: | |

Continuous Index: Within 8" of Joint:

Remarks:

| Code: Description: | DAGS Deposits Attached Grease |
|-----------------------|----------------------------------|
| Distance (ft): | 64.9 |
| Structural Grade: | 0 |
| O&M Grade: | 2 |
| | |

| Structural Grade: | 0 |
|---------------------|-------|
| O&M Grade: | 2 |
| Clock Start/From: | 8 |
| Clock To: | 4 |
| 1st Value: | |
| 2nd Value: | |
| Value Percent: | 5.000 |
| Continuous Index: | F01 |
| Within 8" of Joint: | NO |
| Remarks: | |




| Code: | TF |
|-------------------|-------------|
| Description: | Tap Factory |
| | |
| Distance (ft): | 85.0 |
| Structural Grade: | 0 |
| O&M Grade: | 0 |

Clock Start/From: 10 Clock To: 4.000 1st Value: 4.000 2nd Value: Value Percent: Continuous Index: Vithin 8" of Joint: Remarks:




| Code: Description: | TF Tap Factory |
|-----------------------|-------------------|
| Distance (ft): | 260.7 |
| Structural Grade: | 0 |
| O&M Grade: | 0 |
| Clock Start/From: | 12 |
| Clock To: | |
| 1st Value: | 4.000 |
| 2nd Value: | |
| Value Percent: | |
| Continuous Index: | |
| Within 8" of Joint: | |
| Remarks: | |



Code: MWL Description: Water Level

| Distance (ft): | 302.7 |
|---------------------|--------|
| Structural Grade: | 0 |
| O&M Grade: | 0 |
| Clock Start/From: | |
| Clock To: | |
| 1st Value: | |
| 2nd Value: | |
| Value Percent: | 30.000 |
| Continuous Index: | |
| Within 8" of Joint: | NO |
| Remarks: | |




| Code: Description: | TF Tap Factory |
|-----------------------|-------------------|
| Distance (ft): | 311.5 |
| Structural Grade: | 0 |
| O&M Grade: | 0 |
| Clock Start/From: | 12 |
| Clock To: | |
| 1st Value: | 4.000 |
| 2nd Value: | |
| Value Percent: | |
| Continuous Index: | |
| Within 8" of Joint: | |
| Remarks: | |



| Code: | TF |
|--------------|-------------|
| Description: | Tap Factory |

| Distance (ft): | 326.8 |
|---------------------|-------|
| Structural Grade: | 0 |
| O&M Grade: | 0 |
| Clock Start/From: | 12 |
| Clock To: | |
| 1st Value: | 4.000 |
| 2nd Value: | |
| Value Percent: | |
| Continuous Index: | |
| Within 8" of Joint: | |
| Remarks: | |



| Code: | |
|--------------|--|
| Description: | |

MSA Abandoned Survey

| Distance (ft): | 350.8 |
|---------------------|---------|
| Structural Grade: | 0 |
| O&M Grade: | 0 |
| Clock Start/From: | |
| Clock To: | |
| 1st Value: | |
| 2nd Value: | |
| Value Percent: | |
| Continuous Index: | |
| Within 8" of Joint: | NO |
| Remarks: | UNKNOWN |