Profile/Ph	oto Observation	Report				RedZone
Date:	04/03/2018	Weather:			Coding:	PACP 6.0
Pipe Length (ft): 415.8	Owner:	NA		Pre Clean:	No Pre-Cleaning
P.O.#:		Surveyor:	Jen Costel		PSR:	P-607-081-080
Customer:		Clean Date:	01/01/190	0	Shape:	С
Street:	FOXCROFT STREET		Flow Contro	d:	Not Controlled	
City:	Hobart, IN		Year Renew	ed:		
Location:	Yard		Tape/Media	ı #:		
Purpose:	Routine Assessmer	nt	Dia/Height:		8"	
Use:	Sanitary		Material:		PVC	
Drain Area:	NA		Lining:			
Category:	NA					
Comment:						
Location Detail	s:		Direction of	Survey:	Downstream	
US MH:	M-607-081	DS MH:	M-607-080		Total Length Surveyed (ft)	: 400.5
D&M Index:	2.00	O&M Quick:		2100	O&M Rating:	2.00
Structural Index:	0.00	Structural Qu	uick:	0000	Structural Rating:	0.00
Overall Index:	2.00	Overall Quic	k:	2100	Overall Rating:	2.00

	Position	Code	Observation	Video (sec)	Grade
M(607-	081				
\rightarrow	0. 🖉	AMH	Manhole	10	NA
- ##	√\.0	MWL	Water Level	21	NA
	23.5	MWL	Water Level	80	NA
		MWL	Water Level	136	NA
	57.2	MWL	Water Level	170	NA
- 11	80.7	MWL	Water Level	229	NA
- 11	200.2	MGO	General Observation	482	NA
- 11	282.8	TS	Tap Saddle	659	NA
- 11	376.3	TFA	Tap Factory Active	858	NA
5	376.3	DAGS	Deposits Attached Grease	870	M 2
ecti	385.0	TF	Tap Factory	899	NA
ā	400.5	AMH	Manhole	944	NA
Camera Direction					
M-607-	080				




Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-607-081




Code: MWL Description: Water Level

.0
0
0
5.000
NO



MWL Water Level
23.5
0
0
10.000
NO



Code: MWL Description: Water Level

Distance (ft):	46.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	20.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	

Code:



Description:	Water Level	
Distance (ft):	57.2	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:	5.000	
Continuous Index:		

Within 8" of Joint:

Remarks:

MWL

NO




Code: MWL Description: Water Level

Distance (ft):	80.7
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	20.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	

Code: Description: MGO General Observation




(ft): 200.2	
l Grade: 0	
de: 0	
rt/From:	
:	
<u>e:</u>	
cent:	
us Index:	
of Joint: NO	
REAR CAMER	Α
rt/From: : : : : : : : : : : : : : : : : : :	Α




Code:	TS
Description:	Tap Saddle

Distance (ft):	282.8
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	12
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	




Code:	TFA
Description:	Tap Factory Active
Distance (ft):	376.3
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	12
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	




Code:DAGSDescription:Deposits Attached Grease

Distance (ft):	276.2
Distance (ft):	376.3
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	1
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code: Description:	TF Tap Factory
Distance (ft):	385.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	12
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code: AMH Description: Manhole

Distance (ft):	400.5
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-607-080