Profile/Photo Observation Report



Date: 10/10/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 153.6 Owner: NA Pre Clean: **Not Known** P.O.#: PSR: P-607-084-081 Surveyor: Selasie Honu

Customer: Clean Date: 01/01/1900 Shape: C

Street: S ASH ST & W 12TH ST Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Light Highway Tape/Media #:

Purpose: Routine Assessment Dia/Height: 8"
Use: Sanitary Material: PVC

Drain Area: NA Lining:

Comment: NULL - DC @ MH-M-507-059

NA

Category:

Location Details: Direction of Survey: **Upstream**

US MH: M-607-084 DS MH: M-607-081 Total Length Surveyed (ft): 2.2

0000 0.00 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 0.00 0000 0.00 Overall Rating: Overall Index: Overall Quick:


Position	Code	Observation	Video (sec)	Grade
n(607) 081				
.0	AMH	Manhole	10	NA
0.	MWL	Water Level	21	NA
2.2	MSA	Abandoned Survey	37	NA

Code:



Description:	Manhole
Distance (ft): Structural Grade:	.0 0
O&M Grade: Clock Start/From: Clock To:	0
1st Value: 2nd Value:	
Value Percent: Continuous Index: Within 8" of Joint:	NO
Remarks:	M-607-081

AMH



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:


Remarks:

5.000

NO

Code: MSA

Description: **Abandoned Survey**



Distance (ft): 2.2 Structural Grade: 0

O&M Grade: 0 Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: camera stopped