

## Profile/Photo Observation Report





|                   |                       |             |                       |            |                            |
|-------------------|-----------------------|-------------|-----------------------|------------|----------------------------|
| Date:             | <b>04/14/2018</b>     | Weather:    |                       | Coding:    | <b>PACP 6.0</b>            |
| Pipe Length (ft): |                       | Owner:      | <b>City of Hobart</b> | Pre Clean: | <b>No Pre-Cleaning</b>     |
| P.O.#:            | <b>45-1</b>           | Surveyor:   | <b>M. Pielacha</b>    | PSR:       | <b>M-608-011-M-608-012</b> |
| Customer:         | <b>City of Hobart</b> | Clean Date: |                       | Shape:     | <b>C</b>                   |

|             |                           |               |                       |
|-------------|---------------------------|---------------|-----------------------|
| Street:     | <b>Off 37th Street</b>    | Flow Control: | <b>Not Controlled</b> |
| City:       | <b>Hobart, IN</b>         | Year Renewed: |                       |
| Location:   | <b>Light Highway</b>      | Tape/Media #: | <b>DEP 45</b>         |
| Purpose:    | <b>Routine Assessment</b> | Dia/Height:   | <b>6"</b>             |
| Use:        | <b>Sanitary</b>           | Material:     | <b>PVC</b>            |
| Drain Area: |                           | Lining:       |                       |
| Category:   | <b>NA</b>                 |               |                       |
| Comment:    |                           |               |                       |

|                   |                  |                             |                   |
|-------------------|------------------|-----------------------------|-------------------|
| Location Details: |                  | Direction of Survey:        | <b>Downstream</b> |
| US MH:            | <b>M-608-011</b> | DS MH:                      | <b>M-608-012</b>  |
|                   |                  | Total Length Surveyed (ft): | <b>97.1</b>       |

|                   |             |                   |             |                    |             |
|-------------------|-------------|-------------------|-------------|--------------------|-------------|
| O&M Index:        | <b>0.00</b> | O&M Quick:        | <b>0000</b> | O&M Rating:        | <b>0.00</b> |
| Structural Index: | <b>0.00</b> | Structural Quick: | <b>0000</b> | Structural Rating: | <b>0.00</b> |
| Overall Index:    | <b>0.00</b> | Overall Quick:    | <b>0000</b> | Overall Rating:    | <b>0.00</b> |

|  | Position | Code | Observation | Video (sec) | Grade |
|--|----------|------|-------------|-------------|-------|
|  | .0       | AMH  | Manhole     | 0           | NA    |
|  | .0       | MWL  | Water Level | 7           | NA    |
|  | 97.1     | AMH  | Manhole     | 247         | NA    |
|  |          |      |             |             |       |



Code: **AMH**  
Description: **Manhole**

Distance (ft): **.0**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **NO**  
Remarks: **M-608-011**



|                     |                    |
|---------------------|--------------------|
| Code:               | <b>MWL</b>         |
| Description:        | <b>Water Level</b> |
| Distance (ft):      | <b>.0</b>          |
| Structural Grade:   | <b>0</b>           |
| O&M Grade:          | <b>0</b>           |
| Clock Start/From:   |                    |
| Clock To:           |                    |
| 1st Value:          |                    |
| 2nd Value:          |                    |
| Value Percent:      | <b>5.000</b>       |
| Continuous Index:   |                    |
| Within 8" of Joint: | <b>NO</b>          |
| Remarks:            |                    |

---



|                     |                  |
|---------------------|------------------|
| Code:               | <b>AMH</b>       |
| Description:        | <b>Manhole</b>   |
| Distance (ft):      | <b>97.1</b>      |
| Structural Grade:   | <b>0</b>         |
| O&M Grade:          | <b>0</b>         |
| Clock Start/From:   |                  |
| Clock To:           |                  |
| 1st Value:          |                  |
| 2nd Value:          |                  |
| Value Percent:      |                  |
| Continuous Index:   |                  |
| Within 8" of Joint: | <b>NO</b>        |
| Remarks:            | <b>M-608-012</b> |