## **Profile/Photo Observation Report**



Profile/Photo Observation Report								
Date: Pipe Length (ft) P.O.#: Customer:	04/14/2018 : 45-1 City of Hobart	Weather: Owner: Surveyor: Clean Date:	City of Hobart M. Pielacha	i.	Coding: Pre Clean: PSR: Shape:	PACP 6.0 No Pre-Cleaning M-608-011-M-608-012 C		
Street:	Off 37th Street	Clean Date.	Flow Control:		Not Controlled			
City:	Hobart, IN		Year Renewed:		Not controlled			
Location:	Light Highway		Tape/Media #:		DEP 45			
Purpose:	Routine Assessment		Dia/Height:		6"			
Use:	Sanitary		Material:		PVC			
Drain Area:			Lining:					
Category:	NA							
Comment:								
Location Detail	s:		Direction of Sur	vey:	Downstream			
US MH:	M-608-011	DS MH:	M-608-012	Total Le	ength Surveyed (ft):	97.1		
O&M Index:	0.00	O&M Quick:	00	00	O&M Rating:	0.00		
Structural Index:	0.00	Structural Q		00	Structural Rating:	0.00		
Overall Index:	0.00	Overall Quic		00	Overall Rating:	0.00		
					_			

Friday, October 1, 2021

Pos	sition	Code	Observation	Video (sec)	Grade
M(608)011					
0.	ı	AMH	Manhole	0	NA
0.		MWL	Water Level	7	NA
97.1	1 .	АМН	Manhole	247	NA
Camera Direction  M 608-012					

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-608-011

AMH

Friday, October 1, 2021



Code: MWL
Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO

Remarks:

\_\_\_



Code: AMH
Description: Manhole

Distance (ft): 97.1
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-608-012

Friday, October 1, 2021