


Profile/Ph	oto Observatior	n Report				RedZone
Date: Pipe Length (ft P.O.#:	03/30/2018): 339.2	Weather: Owner: Surveyor:	NA Mark Ru	by	Coding: Pre Clean: PSR:	PACP 6.0 No Pre-Cleaning P-608-040-041
Customer:		Clean Date	e: 01/01/1 9	000	Shape:	С
Street: WASHINGTON ST & ST MARY CIR		Flow Cont	Flow Control:			
City:	Hobart, IN		Year Rene	wed:		
Location:	Light Highway		Tape/Med	ia #:		
Purpose:	Routine Assessme	ent	Dia/Height	t:	10"	
Use:	Sanitary		Material:		PVC	
Drain Area:	NA		Lining:			
Category:	NA					
Comment:	Flow direction wro	Flow direction wrong				
Location Detail	ls:		Direction of	of Survey:	Downstream	
US MH:	M-608-041	DS MH:	M-608-040	Тс	otal Length Surveyed (ft)	: 337.8
D&M Index:	0.00	O&M Quicl	k:	0000	O&M Rating:	0.00
Structural Index:	0.00	Structural (Quick:	0000	Structural Rating:	0.00
Overall Index:	0.00	Overall Qui	ick:	0000	Overall Rating:	0.00





Code:	АМН	
Description:	Manhole	
Distance (ft):	.0	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:		
Continuous Index:		
Within 8" of Joint:	NO	
Remarks:	M-608-041	



Code: MWL Description: Water Level

Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	10.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code: Description:	AMH Manhole
Distance (ft):	337.8
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-608-040