Profile/Photo Observation Report

Location:



Date: 03/26/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 303.5 Owner: NA Pre Clean: **Not Known** P.O.#: Surveyor: **Justin Gonzales** PSR: P-703-002-003

Customer: Clean Date: 01/01/1900 Shape:

PHEASANT RUN DR Flow Control: **Not Controlled** Street:

City: Hobart, IN Year Renewed: Other Tape/Media #:

Purpose: **Not Known** Dia/Height: 10" **PVC** Use: Sanitary Material:

NA Lining: Drain Area:

NA Category:

Comment: **Location Details:** Direction of Survey: **Downstream**

US MH: M-703-003 M-703-002 Total Length Surveyed (ft): DS MH: 296.4

2.00 2K00 120.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 2.00 2K00 120.00 Overall Rating: Overall Index: Overall Quick:

703-0		A B 41.1	N 4 a m la a la	40	NI A
	.0	AMH	Manhole	10	NA
	0.	MWL	Water Level	21	NA
	₩ 4.9	DAZ(S01)	Deposits Attached Other	42	M 2
	10.6	TF	Tap Factory	65	NA
	12.6	DSF	Deposits Settled Fine	81	M 2
	24.8	DSF	Deposits Settled Fine	117	M 2
_	35.9	TFA	Tap Factory Active	150	NA
	82.2	TF	Tap Factory	254	NA
	113.8	TF	Tap Factory	329	NA
	152.1	MWL	Water Level	417	NA
	163.3	MWL	Water Level	451	NA
,	//166.0	TF	Tap Factory	469	NA
	// 186.5	TF	Tap Factory	522	NA
	/ 244.4	TF	Tap Factory	650	NA
	244.6	MWL	Water Level	662	NA
	245.6	MGO	General Observation	675	NA
	248.0	MGO	General Observation	692	NA
	264.5	TF	Tap Factory	737	NA
	296.4	AMH	Manhole	813	NA
	296.4	DAZ(F01)	Deposits Attached Other	824	M 2

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-703-003

 AMH



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

5.000

NO

Code: DAZ

Description: Deposits Attached Other



Distance (ft): 4.9
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 7
Clock To: 5

1st Value: 2nd Value:

Value Percent: 5.000
Continuous Index: S01
Within 8" of Joint: YES
Remarks: WANDER



Description: Tap Factory

Distance (ft): 10.6
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **DSF**

Description: Deposits Settled Fine

Distance (ft): 12.6
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 6

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO



Code: **DSF**

Description: Deposits Settled Fine

Distance (ft): 24.8
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 6

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: TFA

Description: Tap Factory Active

Distance (ft): 35.9
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 2

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Description: Tap Factory

Distance (ft): 82.2
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**

Description: Tap Factory

Distance (ft): 113.8
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: MWL

Description: Water Level

Distance (ft): 152.1
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 20.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: MWL

Description: Water Level

Distance (ft): 163.3
Structural Grade: 0
O&M Grade: 0


Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO



Description: Tap Factory

Distance (ft): 166.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**

Description: Tap Factory

Distance (ft): 186.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Description: Tap Factory

Distance (ft): 244.4
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: MWL

Description: Water Level

Distance (ft): 244.6
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 40.000

Continuous Index:

Within 8" of Joint: NO



Code: MGO

Description: General Observation

Distance (ft): 245.6
Structural Grade: 0
O&M Grade: 0

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Clock Start/From:

Within 8" of Joint: NO

Remarks: **SOAP SUDS**



Code: MGO

Description: General Observation


Distance (ft): 248.0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: TOILET TISSUE



Description: Tap Factory

Distance (ft): 264.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: AMH
Description: Manhole

Distance (ft): 296.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: M-703-002



Code: DAZ

Description: Deposits Attached Other

Distance (ft): 296.4
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 7
Clock To: 5

1st Value: 2nd Value:

Value Percent: 5.000
Continuous Index: F01
Within 8" of Joint: YES

Remarks: WANDER