## **Profile/Photo Observation Report**

Location:



Date: 03/26/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 303.5 Owner: NA Pre Clean: **Not Known** P.O.#: **Justin Gonzales** PSR: P-703-002-003 Surveyor:

Customer: Clean Date: 01/01/1900 Shape:

pheasant run dr Flow Control: **Not Controlled** Street:

City: Hobart, IN Year Renewed: Other Tape/Media #:

Purpose: **Not Known** Dia/Height: 10" **PVC** Use: Sanitary Material:

NΑ Drain Area: Lining:

NA Category:

Comment: **Location Details:** Direction of Survey: **Downstream** 

US MH: M-703-003 M-703-002 Total Length Surveyed (ft): DS MH: 296.4

2.00 2K00 120.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 2.00 2K00 120.00 Overall Rating: Overall Index: Overall Quick:

703-003					
	.0	AMH	Manhole	10	NA
	.0	MWL	Water Level	21	NA
	4.9	DAZ(S01)	Deposits Attached Other	42	M 2
	10.6	TF	Tap Factory	65	NA
	12.6	DSF	Deposits Settled Fine	81	M 2
	24.8	DSF	Deposits Settled Fine	117	M 2
<u> </u>	35.9	TFA	Tap Factory Active	150	NA
	82.2	TF	Tap Factory	254	NA
<b>,</b>	113.8	TF	Tap Factory	329	NA
_	152.1	MWL	Water Level	417	NA
	163.3	MWL	Water Level	451	NA
	166.0	TF	Tap Factory	469	NA
	186.5	TF	Tap Factory	522	NA
<del>-</del>	244.4	TF	Tap Factory	650	NA
	244.6	MWL	Water Level	662	NA
	245.6	MGO	General Observation	675	NA
	248.0	MGO	General Observation	692	NA
	264.5	TF	Tap Factory	737	NA
<b>          </b>	296.4	AMH	Manhole	813	NA
<b>  </b>  /[	296.4	DAZ(F01)	Deposits Attached Other	824	M 2
	296.4	DAZ(F01)	Deposits Attached Other	824	M 2

Code:



Description:	Manhole		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Continuous Index:			
Within 8" of Joint:	NO		
Remarks:	M-703-003		

AMH



Code: MWL

Description: **Water Level** 

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

5.000

NO



Code: DAZ

Description: **Deposits Attached Other** 

Distance (ft): 4.9 Structural Grade: 0 O&M Grade: 2 Clock Start/From: 7 Clock To: 5 1st Value: 2nd Value:

Value Percent: 5.000 Continuous Index: **S01** Within 8" of Joint: YES

Remarks: WANDER



Description: Tap Factory

Distance (ft): 10.6
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **DSF** 

Description: Deposits Settled Fine

Distance (ft): 12.6
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 6

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO



Code: **DSF** 

Description: Deposits Settled Fine

Distance (ft): 24.8
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 6

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: TFA

Description: Tap Factory Active

Distance (ft): 35.9
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 2

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Description: Tap Factory

Distance (ft): 82.2
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF** 

Description: Tap Factory

Distance (ft): 113.8
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: MWL

Description: Water Level

Distance (ft): 152.1
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 20.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: MWL

Description: Water Level

Distance (ft): 163.3 Structural Grade: 0

O&M Grade: **0** 

Clock Start/From: Clock To:

1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO



Description: Tap Factory

Distance (ft): 166.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:


1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Description: Tap Factory



Distance (ft): 186.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Description: Tap Factory

Distance (ft): 244.4
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: MWL

Description: Water Level

Distance (ft): 244.6
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 40.000

Continuous Index:

Within 8" of Joint: NO



Code: MGO

Description: General Observation

Distance (ft): 245.6
Structural Grade: 0
O&M Grade: 0

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Clock Start/From:

Within 8" of Joint: NO

Remarks: **SOAP SUDS** 



Code: MGO

Description: General Observation


Distance (ft): 248.0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: TOILET TISSUE



Description: Tap Factory

Distance (ft): 264.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: AMH
Description: Manhole

Distance (ft): 296.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-703-002



Code: DAZ

Description: Deposits Attached Other

Distance (ft): 296.4
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 7
Clock To: 5

1st Value: 2nd Value:

Value Percent: 5.000
Continuous Index: F01
Within 8" of Joint: YES

Remarks: WANDER