## **Profile/Photo Observation Report**



Date: 03/27/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 371.1 Owner: NA Pre Clean: **Not Known** P.O.#: Surveyor: **Justin Gonzales** PSR: P-703-037-067

Customer: Clean Date: 01/01/1900 Shape: C

Street: **EDGEWATER DR** Flow Control: **Not Controlled** 

City: Hobart, IN Year Renewed:
Location: Other Tape/Media #:

Purpose: Not Known Dia/Height: 10"
Use: Sanitary Material: PVC

Drain Area: **NA** Lining:

Category: NA

Comment:

Location Details: Direction of Survey: Downstream

US MH: M-703-037 DS MH: M-704-067 Total Length Surveyed (ft): 364.3

2.00 2M00 142.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 2.00 2M00 142.00 Overall Rating: Overall Index: Overall Quick:


	Position	Code	Observation	Video (sec)	Grade
703-0	037				
	0.	AMH	Manhole	10	NA
	.0	MWL	Water Level	21	NA
	\\ <u>5.6</u>	DAZ(S01)	Deposits Attached Other	44	M 2
	37.1	TF	Tap Factory	118	NA
	109.3	TF	Tap Factory	275	NA
	/111.8	DAZ(F01)	Deposits Attached Other	291	M 2
Ш.	// 111.8	DAGS(S02)	Deposits Attached Grease	302	M 2
	213.9	TF	Tap Factory	520	NA
	298.3	TF	Tap Factory	702	NA
	364.3	AMH	Manhole	846	NA
	364.3	DAGS(F02)	Deposits Attached Grease	857	M 2

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-703-037

 $\mathsf{AMH}$ 



Code: MWL

Description: **Water Level** 

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:


Continuous Index:

Within 8" of Joint:

Remarks:

10.000

NO




Distance (ft): 5.6 Structural Grade: 0 O&M Grade: 2


Clock Start/From: 7 Clock To: 5

1st Value: 2nd Value:

Value Percent: 5.000 Continuous Index: **S01** Within 8" of Joint: YES

Remarks: WANDER





Code: **TF** 

Description: Tap Factory


Distance (ft): 37.1
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 9

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF** 

Description: Tap Factory

Distance (ft): 109.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: DAZ

Description: Deposits Attached Other

Distance (ft): 111.8
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 7
Clock To: 5
1st Value:

2nd Value:

Value Percent: 5.000
Continuous Index: F01
Within 8" of Joint: YES

Remarks: WANDER



Code: DAGS


Description: Deposits Attached Grease

Distance (ft): 111.8
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 7
Clock To: 5
1st Value:

Value Percent: 5.000
Continuous Index: S02
Within 8" of Joint: YES

2nd Value:

Remarks: WANDER



Code: **TF** 

Description: Tap Factory

Distance (ft): 213.9
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF** 

Description: Tap Factory

Distance (ft): 298.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 9

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: AMH
Description: Manhole

Distance (ft): 364.3
Structural Grade: 0
O&M Grade: 0

Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-704-067



Code: DAGS

Description: Deposits Attached Grease

Distance (ft): 364.3
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 7
Clock To: 5
1st Value:

Value Percent: 5.000
Continuous Index: F02
Within 8" of Joint: YES

2nd Value:

Remarks: WANDER