

## Profile/Photo Observation Report




Date:	<b>10/17/2021</b>	Weather:		Coding:	<b>PACP 7.0</b>
Pipe Length (ft):	<b>24.2</b>	Owner:	<b>City of Hobart</b>	Pre Clean:	<b>Heavy Cleaning</b>
P.O.#:	<b>YES502259</b>	Surveyor:	<b>S. Bucklin</b>	PSR:	<b>P-704-012-009</b>
Customer:	<b>City of Hobart</b>	Clean Date:	<b>10/12/2021</b>	Shape:	<b>C</b>

Street:	<b>East Cleveland Avenue</b>	Flow Control:	<b>Not Controlled</b>
City:	<b>Hobart, IN</b>	Year Renewed:	
Location:	<b>Local rural streets with light traffic, t</b>	Tape/Media #:	
Purpose:	<b>Routine Assessment</b>	Dia/Height:	<b>10"</b>
Use:	<b>Sanitary Sewage Pipe</b>	Material:	<b>VCP</b>
Drain Area:		Lining:	
Category:	<b>NA</b>		
Comment:			
Location Details:		Direction of Survey:	<b>Downstream</b>
US MH:	<b>M-704-012</b>	DS MH:	<b>M-704-009</b>
		Total Length Surveyed (ft):	<b>24.2</b>

O&M Index:	<b>0.00</b>	O&M Quick:	<b>0000</b>	O&M Rating:	<b>0.00</b>
Structural Index:	<b>3.50</b>	Structural Quick:	<b>5233</b>	Structural Rating:	<b>21.00</b>
Overall Index:	<b>3.50</b>	Overall Quick:	<b>5233</b>	Overall Rating:	<b>21.00</b>

	Position	Code	Observation	Video (sec)	Grade
	.0	AMH	Manhole	1	NA
	.0	MWL	Miscellaneous Water Level	61	NA
	2.1	CL	Crack Longitudinal	112	S 2
	5.3	CM	Crack Multiple	174	S 3
	8.3	CM	Crack Multiple	233	S 3
	17.4	CM	Crack Multiple	324	S 3
	20.4	DR(S01)	Deformed Rigid	387	S 5
	23.4	BSV	Broken Soil Visible	486	S 5
	23.5	DR(F01)	Deformed Rigid	513	S 5
	24.2	AMH	Manhole	599	NA




Code: **AMH**  
 Description: **Manhole**  
  
 Distance (ft): **.0**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks: **M-704-012**




Code: **MWL**  
Description: **Miscellaneous Water Level**

Distance (ft): **.0**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent: **5.000**  
Continuous Index:  
Within 8" of Joint: **NO**  
Remarks:



Code: **CL**  
Description: **Crack Longitudinal**


Distance (ft): **2.1**  
Structural Grade: **2**  
O&M Grade: **0**  
Clock Start/From: **1**  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks:



Code: **CM**  
Description: **Crack Multiple**

Distance (ft): **5.3**  
Structural Grade: **3**  
O&M Grade: **0**  
Clock Start/From: **9**  
Clock To: **3**  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks:

---




Code: **CM**  
Description: **Crack Multiple**

Distance (ft): **8.3**  
Structural Grade: **3**  
O&M Grade: **0**  
Clock Start/From: **8**  
Clock To: **4**  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks:


---





Code: **CM**  
 Description: **Crack Multiple**

Distance (ft): **17.4**  
 Structural Grade: **3**  
 O&M Grade: **0**  
 Clock Start/From: **7**  
 Clock To: **2**  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **YES**  
 Remarks:



Code: **DR**  
 Description: **Deformed Rigid**


Distance (ft): **20.4**  
 Structural Grade: **5**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent: **10.000**  
 Continuous Index: **S01**  
 Within 8" of Joint: **NO**  
 Remarks:



Code: **BSV**  
Description: **Broken Soil Visible**

Distance (ft): **23.4**  
Structural Grade: **5**  
O&M Grade: **0**  
Clock Start/From: **1**  
Clock To: **11**  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks:


---



Code: **DR**  
Description: **Deformed Rigid**

Distance (ft): **23.5**  
Structural Grade: **5**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent: **10.000**  
Continuous Index: **F01**  
Within 8" of Joint: **NO**  
Remarks:

---



Code:	<b>AMH</b>
Description:	<b>Manhole</b>
Distance (ft):	<b>24.2</b>
Structural Grade:	<b>0</b>
O&M Grade:	<b>0</b>
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	<b>NO</b>
Remarks:	<b>M-704-009</b>