Profile/Photo Observation Report



Date: 04/21/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 395.3 Owner: NA Pre Clean: **Not Known** P.O.#: Jen Costello PSR: P-704-015-014 Surveyor:

Customer: Clean Date: 01/01/1900 Shape: C

Street: E Home Ave Flow Control: Not Controlled
City: Hobart, IN Year Renewed:

Location: Other Tape/Media #:
Purpose: Not Known Dia/Height: 12"

Use: Sanitary Material: VCP

Drain Area: NA Lining: Category: NA

Comment:

Location Details: Direction of Survey: Downstream

US MH: M-704-014 DS MH: M-704-015 Total Length Surveyed (ft): 17.1

1.00 1100 1.00 O&M Index: O&M Quick: O&M Rating: 4.00 4.00 Structural Quick: Structural Rating: Structural Index: 2.50 5.00 Overall Index: Overall Quick: Overall Rating:

	Position	Code	Observation	Video (sec)	Grade
v(704) 01	L 4				
	.0	AMH	Manhole	10	NA
	0.	MWL	Water Level	21	NA
-	\	LL	Alignment Left	33	M 1
-	16.3	FM	Fracture Multiple	77	S 4
-	17.1	MSA	Abandoned Survey	90	NA

Code:



Description:	Manhole	
Distance (ft):	.0	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:		
Continuous Index:		
Within 8" of Joint:	NO	
Remarks:	M-704-014	

AMH



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From:

Clock To:

1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint: NO

Remarks:

10.000

Code: LL

Alignment Left Description:



Distance (ft): .0

Structural Grade: 0 O&M Grade: 1

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: FM

Description: Fracture Multiple

Distance (ft): 16.3
Structural Grade: 4

O&M Grade: 0

Clock Start/From: 8

Clock To: 11

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: MSA

Description: Abandoned Survey

Distance (ft): 17.1
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: debris under water