## **Profile/Photo Observation Report**



| Profile/Photo Observation Report       |  |   |      |                              |           |   |   |  |
|--|--|---|------|------------------------------|-----------|---|---|--|
| Date: Pipe Length (ft P.O.#: Customer: | 04/28/2018<br>:):<br>129<br>City of Hobart | Weather:<br>Owner:<br>Surveyor:<br>Clean Date | N    | ity of Hobart<br>1. Pielacha |           | Coding:<br>Pre Clean:<br>PSR:<br>Shape: | PACP 6.0<br>No Pre-Cleaning<br>P-704-032-031<br>C |  |
| Street:                                | Old Ridge Road                             |   | Flo  | w Control:                   |           | Not Controlled                          |   |  |
| City:                                  | Hobart, IN                                 |   | Yea  | ar Renewed:                  |           |   |   |  |
| Location:                              | <b>Light Highway</b>                       |   | Тар  | pe/Media #:                  |           | <b>DEP 129</b>                          |   |  |
| Purpose:                               | Routine Assessme                           | nt  | Dia  | a/Height:                    |           | 12"                                     |   |  |
| Use:                                   | Sanitary                                   |   | Ma   | aterial:                     |           | VCP                                     |   |  |
| Drain Area:                            |  |   | Lin  | ing:                         |           |   |   |  |
| Category:                              | NA   |   |      |                              |           |   |   |  |
| Comment:                               | YES501824 Submit                           | al 2  |      |                              |           |   |   |  |
| Location Detai                         | ls:  |   | Dir  | ection of Survey             | :         | Downstream                              |   |  |
| US MH:                                 | M-704-032                                  | DS MH:  | M-70 | 04-031                       | Total Len | gth Surveyed (ft):                      | 154.9   |  |
| O&M Index:                             | 0.00                                       | O&M Quick                                     | ς:   | 0000                         |           | 0&M Rating:                             | 0.00  |  |
| Structural Index:                      | 3.00                                       | Structural (                                  |      | 3100                         |           | tructural Rating:                       | 3.00  |  |
| Overall Index:                         | 3.00                                       | <br>Overall Qui                               |      | 3100                         |           | Overall Rating:                         | 3.00  |  |

Thursday, May 4, 2023 1

| Positio          | n Code | Observation    | Video (sec) | Grade |
|------------------|--------|----------------|-------------|-------|
| M(704-)032       |        |                |             |       |
| .0               | AMH    | Manhole        | 0           | NA    |
| 0.0              | MWL    | Water Level    | 9           | NA    |
| 107.3            | CM     | Crack Multiple | 198         | S 3   |
| 154.8            | AMH    | Manhole        | 379         | NA    |
| Camera Direction |        |                |             |       |


Code:



| Description:        | Manhole   |  |  |
|---------------------|-----------|--|--|
|                     |           |  |  |
| Distance (ft):      | .0        |  |  |
| Structural Grade:   | 0         |  |  |
| O&M Grade:          | 0         |  |  |
| Clock Start/From:   |           |  |  |
| Clock To:           |           |  |  |
| 1st Value:          |           |  |  |
| 2nd Value:          |           |  |  |
| Value Percent:      |           |  |  |
| Continuous Index:   |           |  |  |
| Within 8" of Joint: | NO        |  |  |
| Remarks:            | M-704-032 |  |  |
|                     |           |  |  |

AMH

Thursday, May 4, 2023 2



Code: MWL Description: **Water Level** 

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint: NO

Remarks:

10.000



Code: CM

Description: **Crack Multiple** 

Distance (ft): 107.3 Structural Grade: 3 O&M Grade: 0 Clock Start/From: 12 Clock To: 3 1st Value: 2nd Value: Value Percent:

Continuous Index: Within 8" of Joint:

Remarks:

YES

3 Thursday, May 4, 2023



Code: AMH
Description: Manhole

Distance (ft): 154.8
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-704-032.1

Thursday, May 4, 2023 4