
Date:	10/19/2021	Weather:			Coding:	PACP 6.0
Pipe Length (ft):	Owner:	Hobart, IN		Pre Clean:	Not Known
P.O.#:	900_1	Surveyor:	M. Pielacha		PSR:	P-705-LMP-015
Customer:	Hobart, IN	Clean Date:			Shape:	С
Street:	5th Street		Flow Control:			
City:	Hobart, IN		Year Renewed:			
Location:	Light Highway		Tape/Media #:		900	
Purpose:	Routine Assessment	:	Dia/Height:		8"	
Use:	Sanitary		Material:		VCP	
Drain Area:			Lining:			
Category:	NA					
Comment:						
Location Detai	ls:		Direction of Sur	vey:	Upstream	
US MH:	M-705-15	DS MH:	M-705-15	Total Leng	gth Surveyed (ft):	19.5
)&M Index:	4.00	O&M Quick:	410	00_0	&M Rating:	4.00
tructural Index:	3.00	Structural Qu	244		ructural Rating:	3.00
Overall Index:	3.50	Overall Quick			verall Rating:	7.00





Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-705-15



Code:	MWL
Description:	Water Level
Distance (ft):	0
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code: Description:	CM Crack Multiple
Distance (ft):	10.3
Structural Grade:	3
O&M Grade:	0
Clock Start/From:	10
Clock To:	1
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code: Description:	OBP Obstacle External Pipe or Cable
Distance (ft):	19.5
Structural Grade:	0
O&M Grade:	4
Clock Start/From:	3
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	30.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code: Description:	MSA Abandoned Survey
Distance (ft):	19.5
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	Unable to pass external pipe