Profile/Photo Observation Report



Profile/Pr	noto Observation R	Weather: Owner: City of Hobart Surveyor: Clean Date: Coding: PACP 6.0 Pre Clean: No Pre-Cleaning PSR: P-705-017-016 Shape: C Flow Control: Not Controlled				
Date: Pipe Length (f	05/02/2018 t):		City of Hobar	t	•	
P.O.#:	168	•	M. Pielacha			P-705-017-016
Customer:	City of Hobart	Clean Date:			Shape:	С
Street:	Main Street		Flow Control:		Not Controlled	
City:	Hobart, IN		Year Renewed:			
Location:	Light Highway		Tape/Media #:		DEP 168	
Purpose:	Routine Assessment		Dia/Height:		18"	
Use:	Sanitary		Material:		VCP	
Drain Area:			Lining:			
Category:	NA					
Comment:	5-21-2018					
Location Deta	ils:		Direction of Su	rvey:	Downstream	
US MH:	M-705-016	DS MH:	M-705-017	Total	Length Surveyed (ft):	.1
O&M Index:	0.00	O&M Quick:	00	000	O&M Rating:	0.00
Structural Index	0.00	 _Structural Qu	uick: 00	000	Structural Rating:	0.00
Overall Index:	0.00	 _Overall Quicl	c: 00	000	Overall Rating:	0.00

Thursday, May 4, 2023

Position	Code	Observation	Video (sec)	Grade
M(705-)016				
.0	АМН	Manhole	0	NA
.0	MWL	Water Level	14	NA
0.\	MSA	Abandoned Survey	23	NA
Camera Direction				

Code:



Description: Manhole Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint: NO Remarks: M-705-017

AMH

Thursday, May 4, 2023 2



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint: NO

15.000

Remarks:



Code: MSA

Description: **Abandoned Survey**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From: Clock To:

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks: heavy debris and sediment

3 Thursday, May 4, 2023