Profile/Photo Observation Report



| Profile/Photo Observation Report | | | | | | | |
|----------------------------------|-------------------------|------------------|---------------------|-----------------------------|---------------|--|--|
| Date: | 04/14/2018 | Weather: | | Coding: | PACP 6.0 | | |
| Pipe Length (ft): | | Owner: | City of Hobart | Pre Clean: | Not Known | | |
| P.O.#: | 249 | Surveyor: | B. Helbling | PSR: | P-706-048-017 | | |
| Customer: | City of Hobart | Clean Date: | | Shape: | С | | |
| Street: | Main Street | ı | Flow Control: | Not Controlled | | | |
| City: | Hobart, IN | , | Year Renewed: | | | | |
| Location: | Light Highway | - | Tape/Media #: | DEP249 | | | |
| Purpose: | Routine Assessme | nt [| Dia/Height: | 15" | | | |
| Use: | Sanitary | Ī | Material: | VCP | | | |
| Drain Area: | | I | Lining: | | | | |
| Category: | NA | | | | | | |
| Comment: | YES501824 Submit | tal 2 | | | | | |
| Location Deta | ils: | 1 | Direction of Survey | : Downstream | | | |
| US MH: | M-705-017 | DS MH: M | -706-048 | Total Length Surveyed (ft): | 5.9 | | |
| O&M Index: | 3.00 | O&M Quick: | 3100 | O&M Rating: | 3.00 | | |
| Structural Index | 2.00 | Structural Quick | c: 2100 | Structural Rating: | 2.00 | | |
| Overall Index: | 2.50 | Overall Quick: | 3121 | Overall Rating: | 5.00 | | |
| | | | | | | | |

1 Thursday, May 4, 2023

| Position | Code | Observation | Video (sec) | Grade |
|----------|----------|-----------------------|-------------|-------|
| 705-017 | | | | |
| 0. | AMH | Manhole | 0 | NA |
| 0.\ | MWL | Water Level | 11 | NA |
| 1.9 | DSF(S01) | Deposits Settled Fine | 70 | M 3 |
| 4.1 | CL | Crack Longitudinal | 153 | S 2 |
| 5.9 | DSF(F01) | Deposits Settled Fine | 392 | M 3 |
| 5.9 | MSA | Abandoned Survey | 398 | NA |
| | | | | |



| AMH Manhole | |
|----------------|--|
| | |
| .0 | |
| 0 | |
| 0 | |
| | |
| | |
| | |
| | |
| | |
| | |
| NO | |
| M-706-048 | |
| | |



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0

O&M Grade: **0**

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 20.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: **DSF**

Description: Deposits Settled Fine

Distance (ft): 1.9
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 4
Clock To: 8

1st Value: 2nd Value:

Value Percent: 15.000
Continuous Index: S01
Within 8" of Joint: NO

Remarks:



Code: CL

Description: Crack Longitudinal

Distance (ft): 4.1
Structural Grade: 2
O&M Grade: 0
Clock Start/From: 12

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: **DSF**

Description: Deposits Settled Fine

Distance (ft): 5.9
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 4
Clock To: 8
1st Value:

2nd Value:
Value Percent: 15.000
Continuous Index: F01

Remarks:

Within 8" of Joint:

NO



Code: MSA

Description: Abandoned Survey

Distance (ft): 5.9
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index:
Within 8" of Joint: NO

Remarks: **Heavy sediment**