Profile/Photo Observation Report



Date: 04/21/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 267.7 Owner: NA Pre Clean: **Not Known** P.O.#: PSR: P-705-022-019 Surveyor: **Mark Ruby**

Customer: Clean Date: 01/01/1900 Shape: C

Street: Capitol Flow Control: Not Controlled

City: Hobart, IN Year Renewed: Location: Light Highway Tape/Media #:

Purpose: Maintenance Related Dia/Height: 8"
Use: Sanitary Material: VCP

Drain Area: NA Lining: Cured in Place

Category: NA

Comment: Roots at 109'.-flow reversed.

Location Details: Direction of Survey: **Upstream**

US MH: M-705-019 DS MH: M-705-022 Total Length Surveyed (ft): 111.0

1.62 3224 21.00 O&M Index: O&M Quick: O&M Rating: 3.00 33.00 Structural Quick: Structural Rating: Structural Index: 54.00 2.25 Overall Quick: Overall Rating: Overall Index:

P	osition Co	de	Observation	Video (sec)	Grade
705-022					
. () AM	1H	Manhole	10	NA
, /\ <u>.</u>) M\	ΝL	Water Level	21	NA
\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	.8 CN	1	Crack Multiple	40	S 3
$\sqrt{4}$.6 TB		Tap Break-in	55	NA
1	7.8 CM	1	Crack Multiple	96	S 3
1	9.7 TFI	D	Tap Factory Defective	114	M 2
	9.9 RF.	J(S01)	Roots Fine Joint	128	M 1
3	8.5 RF.	J(F01)	Roots Fine Joint	181	M 1
$\sqrt{4}$	0.4 TF		Tap Factory	198	NA
$\frac{1}{\sqrt{4}}$	4.6 TB	D	Tap Break-in Defective	219	M 3
4	5.3 CN	1	Crack Multiple	234	S 3
1/4	5.8 TB		Tap Break-in	251	NA
4	6.6 TFI	D	Tap Factory Defective	266	M 2
4	8.5 TFI	D	Tap Factory Defective	282	M 2
$\sqrt{4}$	8.5 RM	1L	Roots Medium Lateral	293	M 3
5	6.0 TB		Tap Break-in	322	NA
6	1.7 CM	1	Crack Multiple	349	S 3
6	7.7 FN	1	Fracture Multiple	377	S 4
6	9.3 TF0	С	Tap Factory Capped	394	NA
7	5.8 TB		Tap Break-in	419	NA
7	7.6 TF0	С	Tap Factory Capped	435	NA
8	0.5 CN	1	Crack Multiple	455	S 3
8	2.3 CS		Crack Spiral	474	S 2
8	4.7 CN	1(SO2)	Crack Multiple	495	S 3
9	0.6 RF.	J	Roots Fine Joint	523	M 1
1	00.3 TFI	D	Tap Factory Defective	556	M 2
$\sqrt{1}$	03.1 RF.	J(S03)	Roots Fine Joint	575	M 1
$\frac{1}{\sqrt{1}}$	03.1 CN	1(F02)	Crack Multiple	587	S 3
1	11.0 RF.	J(F03)	Roots Fine Joint	618	M 1
$\sqrt{1}$	11.0 MS	SA	Abandoned Survey	629	NA



Code: AMH
Description: Manhole


Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Clock Start/From:

Within 8" of Joint: NO

Remarks: M-705-022



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint: NO



Description: Crack Multiple

Distance (ft): 3.8
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 1
Clock To: 5

1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: TB

Description: Tap Break-in

Distance (ft): 4.6
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 3

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Description: Crack Multiple

Distance (ft): 17.8
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 9
Clock To: 3
1st Value:

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: **TFD**

Description: Tap Factory Defective

Distance (ft): 19.7
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 9

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks: **Debris**




Description: Roots Fine Joint

Distance (ft): 19.9
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 7
Clock To: 5
1st Value:
2nd Value:
Value Percent:

Continuous Index: **S01**Within 8" of Joint: **YES**


Remarks:



Code: RFJ

Description: Roots Fine Joint

Distance (ft): 38.5 Structural Grade: 0 O&M Grade: 1 Clock Start/From: 7 5 Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: F01 Within 8" of Joint: YES



Code: **TF**

Description: Tap Factory

Distance (ft): 40.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 3

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Distance (ft): 44.6
Structural Grade: 0

O&M Grade: 3

Clock Start/From: 10

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks: **Debris**





Description: Crack Multiple

Distance (ft): 45.3
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 2
Clock To: 4

1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint:

Remarks:



Code: TB

Description: Tap Break-in

Distance (ft): 45.8
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 2

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: **TFD**

Description: Tap Factory Defective

Distance (ft): 46.6
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 9

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks: Roots



Code: **TFD**

Description: Tap Factory Defective

Distance (ft): 48.5
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 4

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks: RML



Code: RML

Description: Roots Medium Lateral

Distance (ft): 48.5
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 4

Clock To: 1st Value: 2nd Value:


Value Percent: 30.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: TB


Description: Tap Break-in

Distance (ft): 56.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 9

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Description: Crack Multiple

Distance (ft): 61.7
Structural Grade: 3

O&M Grade: 0

Clock Start/From: 7

Clock To: 1


1st Value: 2

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: **FM**

Description: Fracture Multiple

Distance (ft): 67.7 Structural Grade: 4 O&M Grade: 0 Clock Start/From: 8 Clock To: 4 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint: YES



Code: TFC

Description: Tap Factory Capped


Distance (ft): 69.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 8

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: TB

Description: Tap Break-in

Distance (ft): 75.8
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 4

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:



Code: TFC

Description: Tap Factory Capped

Distance (ft): 77.6
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 4

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: CM

Description: Crack Multiple

Distance (ft): 80.5
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 10
Clock To: 1
1st Value:
2nd Value:
Value Percent:

Continuous Index: Within 8" of Joint:

thin 8" of Joint: YES



Code: CS

Description: **Crack Spiral**

Distance (ft): 82.3 Structural Grade: 2 O&M Grade: 0 Clock Start/From: 8 Clock To: 3 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

S02

YES



Code: CM

Description: **Crack Multiple**

Distance (ft): 84.7 Structural Grade: 3 O&M Grade: 0 Clock Start/From: 7 5 Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index: Within 8" of Joint:



Description: Roots Fine Joint

Distance (ft): 90.6
Structural Grade: 0

O&M Grade: 1

Clock Start/From: 7

Clock To: 9

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: **TFD**

Description: Tap Factory Defective

Distance (ft): 100.3
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 10

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks: Roots



Description: Roots Fine Joint

Distance (ft): 103.1
Structural Grade: 0

O&M Grade: 1

Clock Start/From: 7

Clock To: 5

1st Value: 2nd Value: Value Percent:

Continuous Index: S03
Within 8" of Joint: YES

Remarks:



Code: CM

Description: Crack Multiple

Distance (ft): 103.1
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 7
Clock To: 5
1st Value:
2nd Value:
Value Percent:

Continuous Index: F02

Within 8" of Joint:



Description: Roots Fine Joint

Distance (ft): 111.0
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 7
Clock To: 5


1st Value: 2nd Value: Value Percent:

Continuous Index: F03
Within 8" of Joint: YES

Remarks:

Code: MSA

Description: Abandoned Survey



Distance (ft): 111.0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO Remarks: RFJ