## **Profile/Photo Observation Report**

0.00

Overall Quick:

Overall Index:



0.00

| Date:             | 04/30/2018                | Weather:           |                    | Coding:                  | PACP 6.0         |
|-------------------|---------------------------|--------------------|--------------------|--------------------------|------------------|
|                   | • •                       | Owner:             | City of Hobart     | Coding:<br>Pre Clean:    |                  |
| Pipe Length (ft)  |                           |                    | City of Hobart     |                          | No Pre-Cleaning  |
| P.O.#:            | 145                       | Surveyor:          | M. Pielacha        | PSR:                     | P-705-046-047    |
| Customer:         | City of Hobart            | Clean Date:        |                    | Shape:                   | С                |
| Street:           | East Street               |                    | Flow Control:      | Not Controlle            | d                |
| City:             | Hobart, IN                |                    | Year Renewed:      |                          |                  |
| Location:         | Light Highway             |                    | Tape/Media #:      | <b>DEP 145</b>           |                  |
| Purpose:          | <b>Routine Assessment</b> |                    | Dia/Height:        | 18"                      |                  |
| Use:              | Sanitary                  |                    | Material:          | VCP                      |                  |
| Drain Area:       |                           |                    | Lining:            |                          |                  |
| Category:         | NA                        |                    |                    |                          |                  |
| Comment:          | 5-21-2018                 |                    |                    |                          |                  |
| Location Details: |                           |                    | Direction of Surve | ey: <b>Downstream</b>    |                  |
| US MH:            | M-705-047                 | DS MH:             | M-705-046          | Total Length Surveyed (f | t): <b>145.3</b> |
| D&M Index:        | 0.00                      | O&M Quick:         | 0000               | O&M Rating:              | 0.00             |
| tructural Index:  | 0.00                      | —<br>Structural Qı | uick: <b>000</b> 0 | Structural Rating        | g: 0.00          |
|                   |                           | _                  |                    |                          | , <u> </u>       |

0000

Overall Rating:

Thursday, May 4, 2023

| Posit   | ion Code | Observation         | Video (sec) | Grade |
|---------|----------|---------------------|-------------|-------|
| 705-047 |          |                     |             |       |
| 0.      | АМН      | Manhole             | 0           | NA    |
| 0./\    | MWL      | Water Level         | 10          | NA    |
| 6.0     | TFA      | Tap Factory Active  | 27          | NA    |
| 48.4    | TF       | Tap Factory         | 93          | NA    |
| 78.5    | TFC      | Tap Factory Capped  | 145         | NA    |
| 90.2    | TF       | Tap Factory         | 205         | NA    |
| 123.8   | ТВА      | Tap Break-in Active | 251         | NA    |
| 126.8   | TF       | Tap Factory         | 264         | NA    |
| 140.9   | MSA      | Abandoned Survey    | 442         | NA    |
|         |          |                     |             |       |
|         |          |                     |             |       |

Code:



| Description:        | Manhole   |  |  |  |
|---------------------|-----------|--|--|--|
|                     |           |  |  |  |
| Distance (ft):      | .0        |  |  |  |
| Structural Grade:   | 0         |  |  |  |
| O&M Grade:          | 0         |  |  |  |
| Clock Start/From:   |           |  |  |  |
| Clock To:           |           |  |  |  |
| 1st Value:          |           |  |  |  |
| 2nd Value:          |           |  |  |  |
| Value Percent:      |           |  |  |  |
| Continuous Index:   |           |  |  |  |
| Within 8" of Joint: | NO        |  |  |  |
| Remarks:            | M-705-047 |  |  |  |
|                     |           |  |  |  |

AMH



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint: NO

Remarks:

Code:

**TFA** 

Description: Tap Factory Active



Distance (ft): 6.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 11

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: **TF** 

Description: Tap Factory

Distance (ft): 48.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 10

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: **TFC** 

Description: Tap Factory Capped

Distance (ft): 78.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: **TF** 

Description: Tap Factory

Distance (ft): 90.2
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 10

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: TBA

Description: Tap Break-in Active

Distance (ft): 123.8
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: **TF** 

Description: Tap Factory

Distance (ft): 126.8
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: MSA

Description: Abandoned Survey

Distance (ft): 140.9
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: sediment/debris