
Profile/Photo Observation Report



Profile/Photo Observation Report								
Date:	05/02/2018	Weather:			Coding:	PACP 6.0		
Pipe Length (ft	t):	Owner:	City of Ho	bart	Pre Clean:	No Pre-Cleaning		
P.O.#:	166	Surveyor:	M. Pielach	na	PSR:	P-805-053-052.1		
Customer:	City of Hobart	Clean Date:			Shape:	С		
Street:	3rd Street		Flow Contro	ol:	Not Controlled			
City:	Hobart, IN		Year Renew	ed:				
Location:	Light Highway		Tape/Media	a #:	DEP 166			
Purpose:	Routine Assessment		Dia/Height:		18"			
Use:	Sanitary		Material:		VCP			
Drain Area:			Lining:					
Category:	NA							
Comment:	5-21-2018							
Location Details:			Direction of	Survey:	Upstream			
US MH:	M-705-052.1	DS MH:	M-805-053	To	otal Length Surveyed (ft)	.1		
O&M Index:	0.00	O&M Quick:		0000	O&M Rating:	0.00		
Structural Index	0.00	Structural Q		0000	Structural Rating:	0.00		
Overall Index:	0.00	Overall Quic		0000	Overall Rating:	0.00		

Thursday, May 4, 2023

Position	Code	Observation	Video (sec)	Grade
M(805-053				
.0	АМН	Manhole	0	NA
0.	MWL	Water Level	5	NA
0.	MSA	Abandoned Survey	10	NA
Camera Direction				



Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-705-52.1

2 Thursday, May 4, 2023



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint: NO

15.000

Remarks:



Code: MSA

Description: **Abandoned Survey**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: Very heavy debris in MH. Needs

cleaned

3 Thursday, May 4, 2023