## **Profile/Photo Observation Report**

0.00

Overall Quick:

Overall Index:



0.00

Date: 04/26/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): Owner: **City of Hobart** Pre Clean: No Pre-Cleaning P.O.#: M. Pielacha PSR: P-705-081-080 107 Surveyor: Customer: **City of Hobart** Clean Date: Shape: **West 3rd Street** Flow Control: **Not Controlled** Street: City: Hobart, IN Year Renewed: Tape/Media #: **DEP 107** Location: **Light Highway** Purpose: **Routine Assessment** Dia/Height: 6" Use: Sanitary Material: **PVC** Drain Area: Lining: Category: NA YES501824 Submital 2 Comment: **Location Details:** Direction of Survey: **Downstream** US MH: M-705-080 DS MH: M-705-081 Total Length Surveyed (ft): 47.1 0.00 0000 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index:

0000

Overall Rating:

Thursday, May 4, 2023 1

Position	n Code	Observation	Video (sec)	Grade
n(705 <del>)</del> 080				
0.	AMH	Manhole	0	NA
0.	MWL	Water Level	9	NA
47.1	АМН	Manhole	184	NA
M-705-081				



Cod	de:	AMH
Des	scription:	Manhole
Dis	tance (ft):	.0
Str	uctural Grade:	0
0&	M Grade:	0
Clo	ck Start/From:	
Clo	ck To:	
1st	Value:	
2nd	d Value:	
Val	ue Percent:	
Cor	ntinuous Index:	
Wit	thin 8" of Joint:	NO
Rer	marks:	M-705-080

Thursday, May 4, 2023 2



Code: MWL

Description: **Water Level** 

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint: NO

Remarks:

5.000



Code: AMH Description: Manhole

Distance (ft): 47.1 Structural Grade: 0 O&M Grade: 0 Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-705-081

3 Thursday, May 4, 2023