

Profile/Ph	oto Observatior	Report			RedZone
Date:	04/18/2018	Weather:		Coding:	PACP 6.0
Pipe Length (ft)	: <b>219.3</b>	Owner:	NA	Pre Clean:	Not Known
P.O.#:		Surveyor:	Byrd Fitzgerald	PSR:	P-706-008.2-008.1
Customer:		Clean Date:	01/01/1900	Shape:	С
Street:	GARFIELD ST & E 8	TH PL	Flow Control:	Not Controlled	
City:	Hobart, IN		Year Renewed:		
Location:	Light Highway		Tape/Media #:		
Purpose:	Maintenance Rela	ted	Dia/Height:	8"	
Use:	Sanitary		Material:	VCP	
Drain Area:	NA		Lining:	Cured in Place	
Category:	NA				
Comment:	roots at 1'.				
Location Detail	s:		Direction of Surve	y: Upstream	
US MH:	M-706-008.1	DS MH:	M-706-008.2	Total Length Surveyed (ft)	2.5
&M Index:	4.00	O&M Quick:	4100	O&M Rating:	4.00
tructural Index:	0.00	Structural Qu	uick: 0000	Structural Rating:	0.00
Verall Index:	4.00	Overall Quick	c 4100	Overall Rating:	4.00





Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-706-008.2




Code: MWL Description: Water Level

.0
0
0
5.000
NO



Code:	RBJ
Description:	<b>Roots Ball Joint</b>
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	4
Clock Start/From:	7
Clock To:	5
1st Value:	
2nd Value:	
Value Percent:	55.000
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code:MSADescription:Abandoned Survey

Distance (ft):	2.5
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	rbj