Profile/Photo Observation Report



Profile/Photo Observation Report								
Date:	10/21/2021	Weather: Owner:	Hobart	IN	Coding: Pre Clean:	PACP 6.0 Not Known		
Pipe Length (ft):			Hobart, IN M. Pielacha					
P.O.#:	938_1	Surveyor:		acna	PSR:	P-706-008.7-002		
Customer:	Hobart, IN	Clean Date:			Shape:	С		
Street: Garfield Street			Flow Con	trol:				
City:	ity: Hobart, IN		Year Renewed:					
Location:	Light Highway		Tape/Media #:		938			
Purpose:	Purpose: Reversal		Dia/Height:		8"			
Use:	se: Sanitary		Material:		VCP			
Drain Area:			Lining:					
Category:	NA							
Comment:								
Location Details:			Direction of Survey:		Downstream			
US MH:	M-706-8.7	DS MH:	M-706-2		Total Length Surveyed (ft)	: 68.5		
O&M Index:	2.00	O&M Quick:		2900	O&M Rating:	18.00		
Structural Index	0.00	 Structural Q	uick:	0000	Structural Rating:	0.00		
Overall Index:	2.00	Overall Quic	:k:	2900	Overall Rating:	18.00		

	Position	Code	Observation	Video (sec)	Grade
706) 8.	7				
$\overline{}$.0	AMH	Manhole	0	NA
	0.	MWL	Water Level	49	NA
ш	17.9	MMC	Material Change	110	NA
ш	22.5	TF	Tap Factory	134	NA
	23.2	DSF(S01)	Deposits Settled Fine	150	M 2
	24.2	MMC	Material Change	161	NA
	68.5	DSF(F01)	Deposits Settled Fine	315	M 3
	68.5	MSA	Abandoned Survey	319	NA
Ш					



Code:	АМН
Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-706-8.7



Code: MWL
Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: MMC


Description: Material Change

Distance (ft): 17.9
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO Remarks: pvc



Code: TF

Description: **Tap Factory**

Distance (ft): 22.5 Structural Grade: 0 O&M Grade: 0 Clock Start/From: 2

Clock To:

1st Value: 4.000

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

NO



DSF Code:


Description: **Deposits Settled Fine**

Distance (ft): 23.2 Structural Grade: 0 O&M Grade: 2 Clock Start/From: 4 Clock To: 8 1st Value:

2nd Value: Value Percent: 10.000 Continuous Index: **S01** Within 8" of Joint: YES

Remarks:

Thursday, May 4, 2023



Code: MMC

Description: Material Change

Distance (ft): 24.2
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO Remarks: vcp



Code: **DSF**

Description: Deposits Settled Fine

Distance (ft): 68.5
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 4
Clock To: 8
1st Value:

Value Percent: 20.000
Continuous Index: F01
Within 8" of Joint: NO

Remarks:

2nd Value:



Code: MSA

Description: Abandoned Survey

Distance (ft): 68.5
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: reverse Complete