4.00

Overall Index:

Overall Quick:



4.00

Overall Rating:

Date: Pipe Length (ft)	10/21/2021):	Weather: Owner:	Hobart, IN	Coding: Pre Clean:	PACP 6.0 Not Known
P.O.#:	945_1	Surveyor:	M. Pielacha	PSR:	P-706-008.9-001
Customer:	Hobart, IN	Clean Date:		Shape:	С
Street:	10th Street		Flow Control:		
City:	Hobart, IN		Year Renewed:		
Location:	Light Highway		Tape/Media #:	945	
Purpose:	Routine Assessment		Dia/Height:	6"	
Use:	Sanitary		Material:	VCP	
Drain Area:			Lining:		
Category:	NA				
Comment:					
Location Detail	s:		Direction of Survey	/: Downstream	
US MH:	M-706-8.9	DS MH:	M-706-8.9	Total Length Surveyed (ft): 5.2
)&M Index:	4.00	O&M Quick:	4100	O&M Rating:	4.00
tructural Index:	0.00	– Structural Qı	uick· 0000	Structural Rating:	0.00

Thursday, May 4, 2023 1

Posit	ion Code	Observation	Video (sec)	Grade
M(-706)8.9				
0.	AMH	Manhole	0	NA
0.	MWL	Water Level	20	NA
3.4	LR	Alignment Right	91	M 4
5.2	MSA	Abandoned Survey	119	NA
M-706-8.9				



Code: Description:	AMH Manhole		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Continuous Index:			
Within 8" of Joint:	NO		
Remarks:	M-706-8.9		

Thursday, May 4, 2023 2



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: LR

Description: Alignment Right

Distance (ft): 3.4
Structural Grade: 0

O&M Grade: 4

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 40.000

Continuous Index:

Within 8" of Joint: NO

Remarks:

Thursday, May 4, 2023 3



Code: MSA

Description: Abandoned Survey

Distance (ft): 5.2
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index: Within 8" of Joint:

Remarks: Can not make bend

NO

Thursday, May 4, 2023