
Profile/Ph	oto Observatio	n Report			RedZone
Date:	04/16/2018	Weather:		Coding:	PACP 6.0
Pipe Length (ft): 192.9	Owner:	NA	Pre Clean:	Not Known
P.O.#:		Surveyor:	Selasie Honu	PSR:	P-706-010.5-010.4
Customer:		Clean Date:	01/01/1900	Shape:	C
Street:	Capitol		Flow Control:	Not Controlled	
City:	Hobart, IN		Year Renewed:		
Location:	Ditch		Tape/Media #:		
Purpose:	Maintenance Rel	ated	Dia/Height:	12"	
Use:	Sanitary		Material:	PVC	
Drain Area:	NA		Lining:	Cured in Place	
Category:	NA				
Comment:	blk silt at 12'. flow	v incorrect.			
Location Detail	ls:		Direction of Survey	: Upstream	
US MH:	M-706-010.4	DS MH:	M-706-010.5	Total Length Surveyed (ft)	: 13.7
0&M Index:	0.00	O&M Quick:	0000	O&M Rating:	0.00
tructural Index:	0.00	Structural Qu	uick: 0000	Structural Rating:	0.00
Overall Index:	0.00	Overall Quick	c: 0000	Overall Rating:	0.00





Code: Description:	AMH Manhole	
Distance (ft):	.0	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:		
Continuous Index:		
Within 8" of Joint:	NO	
Remarks:	M-706-010.5	



Code: MWL Description: Water Level

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: 5.000 Continuous Index: Within 8" of Joint: NO Remarks:



TF Tap Factory
3.3
0
0
2
4.000



Code:	TF
Description:	Tap Factory

Distance (ft):	6.4
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	10
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:	MSA
Description:	Abandoned Survey

Distance (ft):	13.7
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	camera stopped