Profile/Photo Observation Report



Profile/Photo Observation Report							
Date: 04/29/2018 Pipe Length (ft):		Weather: Owner: City of Hobart		Coding: Pre Clean:	PACP 6.0 Not Known		
P.O.#:	260	Surveyor:	B. Helbling	PSR:	P-706-011.8-011.7		
Customer:	City of Hobart	Clean Date:		Shape:	С		
Street:	Lake Street		Flow Control:	Not Controlled	I		
City:	Hobart, IN		Year Renewed:				
Location:	Light Highway		Tape/Media #:	DEP260			
Purpose:	Routine Assessment		Dia/Height:	12"			
Use:	Sanitary		Material:	PVC			
Drain Area:			Lining:				
Category:	NA						
Comment:	5-21-2018						
Location Detai	ils:		Direction of Survey	/: Downstream			
US MH:	M-706-011.8	DS MH: N	1-706-011.7	Total Length Surveyed (ft): 3.9		
O&M Index:	3.00	O&M Quick:	3100	O&M Rating:	3.00		
Structural Index	. 0.00	— Structural Quic	k: 0000	Structural Rating	0.00		
Overall Index:	3.00	Overall Quick:	3100	Overall Rating:	3.00		

1 Thursday, May 4, 2023

	Position	Code	Observation	Video (sec)	Grade
M-706-01	1.8				
	.0	AMH	Manhole	0	NA
	\ <u>.0</u>	MWL	Water Level	8	NA
- 11	1.2	MWL	Water Level	33	NA
- 11	3.8	DSF	Deposits Settled Fine	129	M 3
- 11	3.9	MSA	Abandoned Survey	178	NA
M-706-01	1.7				

Code:



Description:	Manhole		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Continuous Index:			
Within 8" of Joint:	NO		
Remarks:	M-706-011.8		

AMH

Thursday, May 4, 2023 2



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: MWL
Description: Water Level

Distance (ft): 1.2
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 30.000

Continuous Index:

Within 8" of Joint: NO

Remarks:

Thursday, May 4, 2023 3



Code: **DSF**

Description: Deposits Settled Fine

Distance (ft): 3.8
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 4
Clock To: 8

1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

20.000

NO



Code: MSA

Description: Abandoned Survey

Distance (ft): 3.9
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: **Heavy sediment**

Thursday, May 4, 2023 4