## **Profile/Photo Observation Report**



Profile/Photo Observation Report							
Date: Pipe Length ( P.O.#: Customer:	05/02/2018 (ft): 279 City of Hobart	Weather: Owner: Surveyor: Clean Date:	City of Hobart B. Helbling	Coding: Pre Clean: PSR: Shape:	PACP 6.0 Not Known P-706-013-012 C		
Street:	Water Street		Flow Control:	Not Controlled			
City:	Hobart, IN		Year Renewed:				
Location:	<b>Light Highway</b>		Tape/Media #:	DEP279			
Purpose:	Routine Assessment	:	Dia/Height:	12"			
Use:	Sanitary		Material:	PVC			
Drain Area:			Lining:				
Category:	NA						
Comment:	5-21-2018						
Location Details:			Direction of Survey	: Downstream			
US MH:	M-706-012	DS MH:	M-706-013	Total Length Surveyed (ft)	: <b>126.2</b>		
O&M Index:	0.00	O&M Quick:	0000	O&M Rating:	0.00		
Structural Inde	ex: 0.00	 Structural Qui	ck: <b>0000</b>	Structural Rating:	0.00		
Overall Index:	0.00	— Overall Quick:	0000	Overall Rating:	0.00		

Thursday, May 4, 2023

	Position	Code	Observation	Video (sec)	Grade
706				· ·	
M(706-01	.0	АМН	Manhole	0	NA
	\ .0	MWL	Water Level	13	NA
ш	126.2	AMH	Manhole	499	NA
Camera Direction	13				

Code:



Description:	Manhole		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Continuous Index:			
Within 8" of Joint:	NO		
Remarks:	M-706-013		

AMH

Thursday, May 4, 2023 2



Code: MWL
Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: AMH
Description: Manhole

Distance (ft): 126.2
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index:
Within 8" of Joint:

Remarks: M-706-012

NO

Thursday, May 4, 2023 3