Profile/Photo Observation Report



Profile/Photo Observation Report								
Date: Pipe Length (ft) P.O.#: Customer:	10/23/2021): 975_1 Hobart, IN	Weather: Owner: Surveyor: Clean Date:	M. P	art, IN ielacha	Pre Clean: PSR:	PACP 6.0 Not Known P-706-025-024 C		
Street:	Lincoln Street			Control:				
City:	Hobart, IN			enewed:				
Location:	Light Highway			Media #:	975			
Purpose:	Routine Assessment		Dia/H		8"			
Use:	Sanitary		Mater	_	PVC			
Drain Area:	•		Lining	:				
Category:	NA		J					
Comment:								
Location Detail	s:		Direct	ion of Survey	: Upstream			
US MH:	M-706-24	DS MH:	M-706-2	25	Total Length Surveyed (ft):	5.8		
O&M Index:	3.00	O&M Quick:		3100	O&M Rating:	3.00		
Structural Index:	0.00	Structural Qu		0000	Structural Rating:	0.00		
Overall Index:	3.00	Overall Quicl		3100	Overall Rating:	3.00		

	Position	Code	Observation	Video (sec)	Grade
-706-2	25				
	0	AMH	Manhole	0	NA
	0.	DSF(S01)	Deposits Settled Fine	85	M 3
ш	_0	MWL	Water Level	105	NA
ш	4.6	MMC	Material Change	127	NA
ш	4.6	DSF(F01)	Deposits Settled Fine	145	M 4
ш	4.6	MSA	Abandoned Survey	149	NA



Code: Description:	AMH Manhole
D: 1 (6)	
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-706-25



Code: DSF

Description: Deposits Settled Fine

Distance (ft): .0
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 4
Clock To: 8

1st Value: 2nd Value:

Value Percent: 20.000
Continuous Index: S01
Within 8" of Joint: YES

Remarks:



Code: MWL
Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: MMC

Description: Material Change

Distance (ft): 4.6
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO Remarks: vcp



Code: **DSF**

Description: Deposits Settled Fine

NO

Distance (ft): 4.6
Structural Grade: 0
O&M Grade: 4
Clock Start/From: 4
Clock To: 8
1st Value:

2nd Value:
Value Percent:
Continuous Index:
F01

Remarks:

Within 8" of Joint:



Code: MSA

Description: Abandoned Survey

Distance (ft): 4.6
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: deep sediment