

## Profile/Photo Observation Report




|                   |                   |             |                     |            |                      |
|-------------------|-------------------|-------------|---------------------|------------|----------------------|
| Date:             | <b>04/20/2018</b> | Weather:    |                     | Coding:    | <b>PACP 6.0</b>      |
| Pipe Length (ft): | <b>183.8</b>      | Owner:      | <b>NA</b>           | Pre Clean: | <b>Not Known</b>     |
| P.O.#:            |                   | Surveyor:   | <b>Jen Costello</b> | PSR:       | <b>P-706-035-034</b> |
| Customer:         |                   | Clean Date: | <b>01/01/1900</b>   | Shape:     | <b>C</b>             |

|             |                               |               |                       |
|-------------|-------------------------------|---------------|-----------------------|
| Street:     | <b>LAKE ST &amp; E 7TH ST</b> | Flow Control: | <b>Not Controlled</b> |
| City:       | <b>Hobart, IN</b>             | Year Renewed: |                       |
| Location:   | <b>Light Highway</b>          | Tape/Media #: |                       |
| Purpose:    | <b>Maintenance Related</b>    | Dia/Height:   | <b>10"</b>            |
| Use:        | <b>Sanitary</b>               | Material:     | <b>VCP</b>            |
| Drain Area: | <b>NA</b>                     | Lining:       | <b>Cured in Place</b> |
| Category:   | <b>NA</b>                     |               |                       |
| Comment:    | <b>heavy silt at 7'.</b>      |               |                       |

|                   |                  |                             |                   |
|-------------------|------------------|-----------------------------|-------------------|
| Location Details: |                  | Direction of Survey:        | <b>Downstream</b> |
| US MH:            | <b>M-706-034</b> | DS MH:                      | <b>M-706-035</b>  |
|                   |                  | Total Length Surveyed (ft): | <b>8.3</b>        |

|                   |             |                   |             |                    |             |
|-------------------|-------------|-------------------|-------------|--------------------|-------------|
| O&M Index:        | <b>2.00</b> | O&M Quick:        | <b>2100</b> | O&M Rating:        | <b>2.00</b> |
| Structural Index: | <b>0.00</b> | Structural Quick: | <b>0000</b> | Structural Rating: | <b>0.00</b> |
| Overall Index:    | <b>2.00</b> | Overall Quick:    | <b>2100</b> | Overall Rating:    | <b>2.00</b> |


|  | Position  | Code | Observation              | Video (sec) | Grade |
|--|-----------|------|--------------------------|-------------|-------|
|  | M-706-034 |      |                          |             |       |
|  | .0        | AMH  | Manhole                  | 10          | NA    |
|  | .0        | MWL  | Water Level              | 21          | NA    |
|  | .0        | DAGS | Deposits Attached Grease | 32          | M 2   |
|  | 8.3       | MSA  | Abandoned Survey         | 60          | NA    |
| M-706-035  |           |      |                          |             |       |



Code: **AMH**  
Description: **Manhole**  
  
Distance (ft): **.0**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **NO**  
Remarks: **M-706-034**

---

|              |                    |
|--------------|--------------------|
| Code:        | <b>MWL</b>         |
| Description: | <b>Water Level</b> |



|                     |               |
|---------------------|---------------|
| Distance (ft):      | <b>.0</b>     |
| Structural Grade:   | <b>0</b>      |
| O&M Grade:          | <b>0</b>      |
| Clock Start/From:   |               |
| Clock To:           |               |
| 1st Value:          |               |
| 2nd Value:          |               |
| Value Percent:      | <b>30.000</b> |
| Continuous Index:   |               |
| Within 8" of Joint: | <b>NO</b>     |
| Remarks:            |               |

---

|              |                                 |
|--------------|---------------------------------|
| Code:        | <b>DAGS</b>                     |
| Description: | <b>Deposits Attached Grease</b> |



|                     |               |
|---------------------|---------------|
| Distance (ft):      | <b>.0</b>     |
| Structural Grade:   | <b>0</b>      |
| O&M Grade:          | <b>2</b>      |
| Clock Start/From:   | <b>8</b>      |
| Clock To:           | <b>4</b>      |
| 1st Value:          |               |
| 2nd Value:          |               |
| Value Percent:      | <b>10.000</b> |
| Continuous Index:   |               |
| Within 8" of Joint: | <b>NO</b>     |
| Remarks:            |               |

---



|                     |                           |
|---------------------|---------------------------|
| Code:               | <b>MSA</b>                |
| Description:        | <b>Abandoned Survey</b>   |
| Distance (ft):      | <b>8.3</b>                |
| Structural Grade:   | <b>0</b>                  |
| O&M Grade:          | <b>0</b>                  |
| Clock Start/From:   |                           |
| Clock To:           |                           |
| 1st Value:          |                           |
| 2nd Value:          |                           |
| Value Percent:      |                           |
| Continuous Index:   |                           |
| Within 8" of Joint: | <b>NO</b>                 |
| Remarks:            | <b>debris under water</b> |