

Date:	04/14/2018	Weather:		Coding:	PACP 6.0
			NA	Pre Clean:	Not Known
Pipe Length (ft	.): 181.5	Owner:			
P.O.#:		Surveyor:	Jen Costello	PSR:	P-706-054-UNK
Customer:		Clean Date:	01/01/1900	Shape:	C
Street:	Capitol		Flow Control:	Not Controlle	d
City:	Hobart, IN		Year Renewed:		
Location:	Light Highway		Tape/Media #:		
Purpose:	Maintenance Rela	ated	Dia/Height:	8"	
Use:	Sanitary		Material:	PVC	
Drain Area:	NA		Lining:	Cured in Place	e
Category:	NA				
Comment:					
Location Detai	ls:		Direction of Surv	vey: Upstream	
US MH:	M-706-054	DS MH:	M-706-055	Total Length Surveyed (f	t): 180.9
D&M Index:	0.00	O&M Quick:	000	00 O&M Rating:	0.00
Structural Index	0.00	Structural Q			.: 0.00
Overall Index:	0.00	Overall Quic		00 Overall Rating:	0.00

	Position	Code	Observation	Video (sec)	Grade
M(706-	055				
	0.	AMH	Manhole	10	NA
- 11	.0	MWL	Water Level	21	NA
- 11	.8	TFA	Tap Factory Active	35	NA
	27.4	MWL	Water Level	100	NA
	34.4	TFA	Tap Factory Active	126	NA
	34.4	MWL	Water Level	137	NA
	41.5	TFA	Tap Factory Active	165	NA
	65.3	TF	Tap Factory	226	NA
	139.5	TFA	Tap Factory Active	386	NA
5	142.1	TFA	Tap Factory Active	403	NA
ecti	180.9	AMH	Manhole	492	NA
Camera Direction					
M(706)	054				



Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-706-055



Code: MWL Description: Water Level

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: 10.000 Continuous Index: Within 8" of Joint: NO Remarks:



Code: Description:	TFA Tap Factory Active
Distance (ft):	.8
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	3
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	

Tuesday, December 8, 2020




Code: MWL Description: Water Level

Distance (ft):	27.4
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	30.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	


Code:	TFA
Description:	Tap Factory Active
Distance (ft)	34 4

Distance (It).	34.4
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	3
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	
	Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint:




Code: MWL Description: Water Level

Distance (ft):	34.4
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	




Code:	TFA
Description:	Tap Factory Active
Distance (ft):	41.5
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	3
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	




Code:	TF
Description:	Tap Factory

Distance (ft):	65.3
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	3
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	
Netharks.	



Code:	TFA
Description:	Tap Factory Active
Distance (ft):	139.5
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	3
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code: Description: TFA Tap Factory Active

Distance (ft):	142.1
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	3
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:	AMH
Description:	Manhole

Distance (ft):	180.9
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-706-054