

## Profile/Photo Observation Report




|                   |                   |             |                     |            |                        |
|-------------------|-------------------|-------------|---------------------|------------|------------------------|
| Date:             | <b>04/11/2018</b> | Weather:    |                     | Coding:    | <b>PACP 6.0</b>        |
| Pipe Length (ft): | <b>75.9</b>       | Owner:      | <b>NA</b>           | Pre Clean: | <b>No Pre-Cleaning</b> |
| P.O.#:            |                   | Surveyor:   | <b>Jen Costello</b> | PSR:       | <b>P-706-062-063</b>   |
| Customer:         |                   | Clean Date: | <b>01/01/1900</b>   | Shape:     | <b>C</b>               |

|             |  |               |                       |
|-------------|--|---------------|-----------------------|
| Street:     | <b>FOXCROFT STREET</b>                 | Flow Control: | <b>Not Controlled</b> |
| City:       | <b>Hobart, IN</b>                      | Year Renewed: |                       |
| Location:   | <b>Yard</b>                            | Tape/Media #: |                       |
| Purpose:    | <b>Routine Assessment</b>              | Dia/Height:   | <b>8"</b>             |
| Use:        | <b>Sanitary</b>                        | Material:     | <b>PVC</b>            |
| Drain Area: | <b>NA</b>                              | Lining:       |                       |
| Category:   | <b>NA</b>                              |               |                       |
| Comment:    | <b>Flow direction is marked wrong.</b> |               |                       |

|                   |                  |                             |                   |
|-------------------|------------------|-----------------------------|-------------------|
| Location Details: |                  | Direction of Survey:        | <b>Downstream</b> |
| US MH:            | <b>M-706-063</b> | DS MH:                      | <b>M-706-062</b>  |
|                   |                  | Total Length Surveyed (ft): | <b>74.8</b>       |

|                   |             |                   |             |                    |             |
|-------------------|-------------|-------------------|-------------|--------------------|-------------|
| O&M Index:        | <b>2.00</b> | O&M Quick:        | <b>2300</b> | O&M Rating:        | <b>6.00</b> |
| Structural Index: | <b>0.00</b> | Structural Quick: | <b>0000</b> | Structural Rating: | <b>0.00</b> |
| Overall Index:    | <b>2.00</b> | Overall Quick:    | <b>2300</b> | Overall Rating:    | <b>6.00</b> |

|  | Position | Code      | Observation              | Video (sec) | Grade |
|--|----------|-----------|--------------------------|-------------|-------|
|  |          |           |                          |             |       |
|  | .0       | AMH       | Manhole                  | 10          | NA    |
|  | .0       | MWL       | Water Level              | 21          | NA    |
|  | .0       | DAGS(S01) | Deposits Attached Grease | 32          | M 2   |
|  | 15.9     | DAGS(F01) | Deposits Attached Grease | 75          | M 2   |
|  | 74.8     | AMH       | Manhole                  | 204         | NA    |

Code: **AMH**  
Description: **Manhole**



Distance (ft): **.0**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **NO**  
Remarks: **M-706-063**

---

|              |                    |
|--------------|--------------------|
| Code:        | <b>MWL</b>         |
| Description: | <b>Water Level</b> |



|                     |              |
|---------------------|--------------|
| Distance (ft):      | <b>.0</b>    |
| Structural Grade:   | <b>0</b>     |
| O&M Grade:          | <b>0</b>     |
| Clock Start/From:   |              |
| Clock To:           |              |
| 1st Value:          |              |
| 2nd Value:          |              |
| Value Percent:      | <b>5.000</b> |
| Continuous Index:   |              |
| Within 8" of Joint: | <b>NO</b>    |
| Remarks:            |              |

---

|              |                                 |
|--------------|---------------------------------|
| Code:        | <b>DAGS</b>                     |
| Description: | <b>Deposits Attached Grease</b> |



|                     |              |
|---------------------|--------------|
| Distance (ft):      | <b>.0</b>    |
| Structural Grade:   | <b>0</b>     |
| O&M Grade:          | <b>2</b>     |
| Clock Start/From:   | <b>5</b>     |
| Clock To:           | <b>7</b>     |
| 1st Value:          |              |
| 2nd Value:          |              |
| Value Percent:      | <b>5.000</b> |
| Continuous Index:   | <b>S01</b>   |
| Within 8" of Joint: | <b>NO</b>    |
| Remarks:            |              |

---

Code: **DAGS**  
Description: **Deposits Attached Grease**



Distance (ft): **15.9**  
Structural Grade: **0**  
O&M Grade: **2**  
Clock Start/From: **5**  
Clock To: **7**  
1st Value:  
2nd Value:  
Value Percent: **5.000**  
Continuous Index: **F01**  
Within 8" of Joint: **NO**  
Remarks:

---

Code: **AMH**  
Description: **Manhole**



Distance (ft): **74.8**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **NO**  
Remarks: **M-706-062**