Profile/Ph	ioto Observatio	n Report			RedZor
Date:	03/30/2018	Weather:		Coding:	PACP 6.0
Pipe Length (ft	:): 345.8	Owner:	NA	Pre Clear	n: Not Known
P.O.#:		Surveyor:	Jen Costello	PSR:	P-707-003-002
Customer:		Clean Date	: 01/01/1900	Shape:	С
Street:	E 14TH ST	Flow Control:		Not Cont	rolled
City:	Hobart, IN		Year Renewed:		
Location:	Light Highway		Tape/Media #:		
Purpose:	Maintenance Rela	ated	Dia/Height:	10"	
Use:	Sanitary		Material:	PVC	
Drain Area:	NA		Lining:	Cured in	Place
Category:	NA				
Comment:	Flow direction wr	ong. Reverse se	tup.		
Location Detai	ls:		Direction of Sur	rvey: Upstrean	n
US MH:	M-707-002	DS MH:	M-707-003	Total Length Survey	ed (ft): 306.1
O&M Index:	2.00	O&M Quick	: 24	00 O&M Rating	g: 8.00
Structural Index	. 0.00	Structural C	Quick: 00		0.00
Overall Index:	2.00	Overall Qui	ck: 24	00 Overall Rati	ng: 8.00

M(707-00			Observation	Video (sec)	Grade
VIF/U/-UU	3				
	.0	AMH	Manhole	10	NA
	.0	MWL	Water Level	21	NA
	51.3	IS	Infil Stain	135	NA
	75.7	MGO	General Observation	197	NA
	126.1	TF	Tap Factory	309	NA
	223.8	DAE	Deposits Attached Encrustation	515	M 2
	223.8	IW	Infil Weeper	526	M 2
	248.9	IW	Infil Weeper	587	M 2
	248.9	DAE	Deposits Attached Encrustation	597	M 2
5 L /	261.6	TF	Tap Factory	634	NA
	306.1	MSA	Abandoned Survey	737	NA
Camera Direction					



Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-707-003



Code: MWL Description: Water Level

Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	




Code: Description:	IS Infil Stain
Distance (ft):	51.3
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	




Code:MGODescription:General Observation

75.7
0
0
NO
REAR CAMERA




Code:	TF
Description:	Tap Factory
Distance (ft):	100 1
Distance (ft):	126.1
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	1
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	




Code:DAEDescription:Deposits Attached Encrustation

Distance (ft):	223.8
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	




Code:	IW
Description:	Infil Weeper
Distance (ft):	223.8
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	8
Clock To:	4
	4
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	




Code:IWDescription:Infil Weeper

Distance (ft):	248.9
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code:	DAE
Description:	Deposits Attached Encrustation

Distance (ft):	248.9
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	10.000
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code:	TF
Description:	Tap Factory

Distance (ft):	261.6
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	1
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
value Percent.	
Continuous Index:	



Code:	MS
Description:	Ab

MSA Abandoned Survey

Distance (ft):	306.1
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	UNKNOWN