Profile/Photo Observation Report



Date: 04/11/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 245.4 Owner: NA Pre Clean: **Not Known** P.O.#: Jen Costello PSR: P-707-008-009 Surveyor:

Customer: Clean Date: 01/01/1900 Shape: C

Street: Capitol Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Light Highway Tape/Media #:

Purpose: Maintenance Related Dia/Height: 12"
Use: Sanitary Material: PVC

Drain Area: NA Lining: Cured in Place

Category: NA
Comment: battery at 189'.-flow incorrect

Location Details: Direction of Survey: **Upstream**

US MH: M-707-009 DS MH: M-707-008 Total Length Surveyed (ft): 190.7

2.00 2300 6.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Rating: Structural Index: Structural Quick: 2.00 2300 6.00 Overall Index: Overall Quick: Overall Rating:

	Position	Code	Observation	Video (sec)	Grade
707	008				
\bigvee	0. //	AMH	Manhole	10	NA
ш	0.	MWL	Water Level	21	NA
ш	38.2	TF	Tap Factory	109	NA
ш	100.3	TF	Tap Factory	246	NA
	/ 105.0	DAE	Deposits Attached Encrustation	267	M 2
ш	105.0	IW	Infil Weeper	278	M 2
ш	155.5	TF	Tap Factory	391	NA
ш	178.6	TF	Tap Factory	449	NA
ш	179.3	DAGS	Deposits Attached Grease	463	M 2
ш	190.7	MSA	Abandoned Survey	497	NA
	j III				

Code:



Description:	Manhole		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Continuous Index:			
Within 8" of Joint:	NO		
Remarks:	M-707-008		

AMH



Code: MWL
Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5

Continuous Index:

Within 8" of Joint:


Remarks:

5.000

NO

Code: **TF**

Description: Tap Factory



Distance (ft): 38.2
Structural Grade: 0

O&M Grade: 0


Clock Start/From: 1

Clock To:

Remarks:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: **TF**

Description: Tap Factory

Distance (ft): 100.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 1

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: DAE

Description: Deposits Attached Encrustation

Distance (ft): 105.0
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 4
1st Value:


2nd Value: Value Percent:

alue Percent: 10.000

Continuous Index:

Within 8" of Joint: YES

Remarks:



Code: IW

Description: Infil Weeper

Distance (ft): 105.0
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 4
1st Value:
2nd Value:

Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: **TF**

Description: Tap Factory


Distance (ft): 155.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 1

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**

Description: Tap Factory

Distance (ft): 178.6
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 1

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: DAGS

Description: Deposits Attached Grease

Distance (ft): 179.3
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 4
1st Value:
2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: MSA

Description: Abandoned Survey

Distance (ft): 190.7
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks: UNKNOWN

NO