


Profile/Ph	oto Observatior	n Report				RedZon
Date:	04/15/2018	Weather:			Coding:	PACP 6.0
Pipe Length (ft	:): <b>231.7</b>	Owner:	NA		Pre Clean:	Not Known
P.O.#:		Surveyor:	Selasie Ho	nu	PSR:	P-707-015-016
Customer:		Clean Date	: <b>01/01/19</b> 0	00	Shape:	с
Street:	GARFIELD ST		Flow Contro	ol:	Not Controlled	
City:	Hobart, IN		Year Renew			
Location:	Light Highway		Tape/Media #:			
Purpose: Maintenance Related		Dia/Height:		12"		
Use:	Sanitary		Material:		VCP	
Drain Area:	NA		Lining:		Cured in Place	
Category:	NA					
Comment:	unknown at 3'.					
Location Details:			Direction of Survey:		Upstream	
US MH:	M-707-016	DS MH:	M-707-015	То	tal Length Surveyed (ft):	5.0
0&M Index:	0.00	O&M Quick	:	0000	O&M Rating:	0.00
tructural Index	0.00	Structural C	Juick:	0000	Structural Rating:	0.00
Overall Index:	0.00	Overall Qui		0000	Overall Rating:	0.00






Code: Description:	AMH Manhole		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Continuous Index:			
Within 8" of Joint:	NO		
Remarks:	M-707-015		



Code: MWL Description: Water Level

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: 5.000 Continuous Index: Within 8" of Joint: NO Remarks:

Code:



Description:	Abandoned Survey		
Distance (ft):	5.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Continuous Index:			
Within 8" of Joint:	NO		
Remarks:	camera stopped		

MSA