## **Profile/Photo Observation Report**



Date: 04/13/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 230.8 Owner: NA Pre Clean: **Not Known** P.O.#: P-707-031-032 Jen Costello PSR: Surveyor:

Customer: Clean Date: 01/01/1900 Shape: C

Street: Capitol Flow Control: Not Controlled

City: Hobart, IN Year Renewed: Location: Light Highway Tape/Media #:

Purpose: Maintenance Related Dia/Height: 8"
Use: Sanitary Material: VCP

Drain Area: NA Lining: Cured in Place

Category: NA

Comment: heavy sludge at 3'.-flow incorrect.


Location Details: Direction of Survey: Upstream

US MH: M-707-032 DS MH: M-707-031 Total Length Surveyed (ft): 4.5

0000 0.00 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 0.00 0000 0.00 Overall Index: Overall Quick: Overall Rating:


Position	Code	Observation	Video (sec)	Grade
M(707-)031				
.0	AMH	Manhole	10	NA
0.	MWL	Water Level	21	NA
4.5	MSA	Abandoned Survey	42	NA
M(707)032				

Code:



Description:	Manhole
Distance (ft): Structural Grade:	.0 0
O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent:	0
Continuous Index: Within 8" of Joint: Remarks:	NO M-707-031

**AMH** 



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:


Within 8" of Joint:

Remarks:

10.000

NO





Distance (ft): 4.5
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks: debris under water

NO