Profile/Photo Observation Report



Date: 04/11/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 283.8 Owner: NA Pre Clean: **Not Known** P.O.#: Jen Costello PSR: P-707-078-036 Surveyor:

Customer: Clean Date: 01/01/1900 Shape: C

Street: **E 13TH ST** Flow Control: **Not Controlled**

City: Hobart, IN Year Renewed: Location: Light Highway Tape/Media #:

Purpose: Maintenance Related Dia/Height: 12"
Use: Sanitary Material: VCP

Drain Area: NA Lining: Cured in Place

Category: NA

Comment: Reverse setup. heavy silt caused rollover at 4'.

Location Details: Direction of Survey: **Downstream**

US MH: M-707-036 DS MH: M-707-078 Total Length Surveyed (ft): 5.1

2.00 2200 4.00 O&M Index: O&M Quick: O&M Rating: 2.00 2100 2.00 Structural Quick: Structural Rating: Structural Index: 2.00 2300 6.00 Overall Index: Overall Quick: Overall Rating:

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-707-036

 AMH



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: DAE

Description: **Deposits Attached Encrustation**

Distance (ft): 2.3 Structural Grade: 0 O&M Grade: 2 Clock Start/From: 1 Clock To: 4 1st Value:

2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: YES

Remarks:



Code: CL

Description: Crack Longitudinal

Distance (ft): 3.9
Structural Grade: 2
O&M Grade: 0
Clock Start/From: 10

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES

YES



Code: IW

Description: Infil Weeper

Distance (ft):

Structural Grade:

O&M Grade:

Clock Start/From:

Clock To:

1st Value:


2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:



Code: MSA

Description: Abandoned Survey

Distance (ft): 5.1
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index:

Within 8" of Joint: NO Remarks: debris