## **Profile/Photo Observation Report**



Date: 04/15/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 290.3 Owner: NA Pre Clean: **Not Known** P.O.#: PSR: P-707-040-075 Surveyor: Selasie Honu

Customer: Clean Date: 01/01/1900 Shape: C

Street: STATE ST Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Light Highway Tape/Media #:

Purpose: Maintenance Related Dia/Height: 10"
Use: Sanitary Material: VCP

Drain Area: NA Lining: Cured in Place Category: NA

Comment: 12" pipe


Location Details: Direction of Survey: Downstream

US MH: M-707-040 DS MH: M-707-075 Total Length Surveyed (ft): 6.5

0000 0.00 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 0.00 0000 0.00 Overall Rating: Overall Index: Overall Quick:


	Position	Code	Observation	Video (sec)	Grade
M(707-)04	0				
	.0	AMH	Manhole	10	NA
	.0	MWL	Water Level	21	NA
	6.5	MSA	Abandoned Survey	45	NA
M-707-07	5				

Code:



Description:	Manhole
Distance (ft): Structural Grade:	.0 0
O&M Grade: Clock Start/From: Clock To: 1st Value:	0
2nd Value: Value Percent: Continuous Index: Within 8" of Joint: Remarks:	NO M-707-040

**AMH** 



Code: MWL

Description: **Water Level** 

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:


Value Percent:

Continuous Index:

Within 8" of Joint: NO

Remarks:

5.000



Code: MSA

Description: **Abandoned Survey** 

Distance (ft): 6.5 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To:

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: camera stopped