Profile/Photo Observation Report



Date: 04/06/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 310.3 Owner: NA Pre Clean: **Not Known** P.O.#: PSR: P-707-046-047 Surveyor: Jen Costello

Customer: Clean Date: 01/01/1900 Shape: C

Street: 13th Flow Control: Not Controlled

City: Hobart, IN Year Renewed: Location: Light Highway Tape/Media #:

Purpose: Maintenance Related Dia/Height: 8"
Use: Sanitary Material: PVC

Drain Area: NA Lining: Cured in Place

Category: NA

Comment: Flow direction wrong. Reverse setup.


Location Details: Direction of Survey: **Downstream**

US MH: M-707-047 DS MH: M-707-046 Total Length Surveyed (ft): 305.0

2.00 2900 18.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Index: Structural Quick: Structural Rating: 2.00 2900 18.00 Overall Index: Overall Quick: Overall Rating:


	Position	Code	Observation	Video (sec)	Grade
707-	047				
\checkmark	0.	AMH	Manhole	10	NA
ш	0.	MWL	Water Level	21	NA
	\\.0	DAGS(S01)	Deposits Attached Grease	32	M 2
ш	24.8	TF	Tap Factory	94	NA
ш	33.0	DAGS(F01)	Deposits Attached Grease	122	M 2
ш	117.0	TFA	Tap Factory Active	302	NA
ш	119.0	TF	Tap Factory	318	NA
ш	//134.7	TF	Tap Factory	362	NA
Ш.	//216.2	DAGS	Deposits Attached Grease	536	M 2
 	217.0	TF	Tap Factory	549	NA
	217.5	DAGS	Deposits Attached Grease	561	M 2
ш	220.4	TF	Tap Factory	578	NA
ш	305.0	AMH	Manhole	757	NA

Code:



Description:	Manhole		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Continuous Index:			
Within 8" of Joint:	NO		
Remarks:	M-707-047		

AMH



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.

Continuous Index:

Within 8" of Joint:


Remarks:

5.000

NO

Code: DAGS

Description: Deposits Attached Grease




Distance (ft): .0
Structural Grade: 0
O&M Grade: 2

O&M Grade: 2
Clock Start/From: 7
Clock To: 5

1st Value: 2nd Value:

Value Percent: 5.000
Continuous Index: S01
Within 8" of Joint: NO



Description: Tap Factory

Distance (ft): 24.8
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:

1st Value:


2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:




Description: Deposits Attached Grease

4.000



Distance (ft): 33.0
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 7
Clock To: 5
1st Value:

2nd Value:
Value Percent: 5.000
Continuous Index: F01
Within 8" of Joint: NO



Description: Tap Factory Active


Distance (ft): 117.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**


Description: Tap Factory

Distance (ft): 119.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Description: Tap Factory

Distance (ft): 134.7
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value:

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Description: Deposits Attached Grease

4.000




Distance (ft): 216.2
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 10

1st Value: 2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint: YES



Description: Tap Factory


Distance (ft): 217.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 11

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: DAGS

Description: Deposits Attached Grease


Distance (ft): 217.5
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 10

1st Value: 2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint: NO



Description: Tap Factory

Distance (ft): 220.4
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: AMH
Description: Manhole

Distance (ft): 305.0
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-707-046