

# Profile/Photo Observation Report



Date:	<b>10/21/2021</b>	Weather:		Coding:	<b>PACP 6.0</b>
Pipe Length (ft):		Owner:	<b>Hobart, IN</b>	Pre Clean:	<b>Not Known</b>
P.O.#:	<b>942_2</b>	Surveyor:	<b>M. Pielacha</b>	PSR:	<b>P-707-074-010.6</b>
Customer:	<b>Hobart, IN</b>	Clean Date:		Shape:	<b>C</b>

Street:	<b>State Street</b>	Flow Control:			
City:	<b>Hobart, IN</b>	Year Renewed:			
Location:	<b>Light Highway</b>	Tape/Media #:	<b>942</b>		
Purpose:	<b>Routine Assessment</b>	Dia/Height:	<b>12"</b>		
Use:	<b>Sanitary</b>	Material:	<b>VCP</b>		
Drain Area:		Lining:			
Category:	<b>NA</b>				
Comment:					
Location Details:		Direction of Survey:	<b>Downstream</b>		
US MH:	<b>M-707-74</b>	DS MH:	<b>M-706-10.6</b>	Total Length Surveyed (ft):	<b>50.0</b>

O&M Index:	<b>3.00</b>	O&M Quick:	<b>3200</b>	O&M Rating:	<b>6.00</b>
Structural Index:	<b>3.00</b>	Structural Quick:	<b>4131</b>	Structural Rating:	<b>9.00</b>
Overall Index:	<b>3.00</b>	Overall Quick:	<b>4133</b>	Overall Rating:	<b>15.00</b>

Position	Code	Observation	Video (sec)	Grade
M-707-74				
.0	AMH	Manhole	0	NA
.0	MWL	Water Level	8	NA
8.6	CM	Crack Multiple	89	S 3
10.8	DSF(S01)	Deposits Settled Fine	186	M 3
19.8	DSF(F01)	Deposits Settled Fine	262	M 3
19.8	FH2(S02)	Fracture Longitudinal Hinge, 2	272	S 4
23.6	FH2(F02)	Fracture Longitudinal Hinge, 2	290	S 4
23.6	CL	Crack Longitudinal	293	S 2
44.7	MMC	Material Change	322	NA
50.0	AMH	Manhole	350	NA




Code: **AMH**  
Description: **Manhole**

Distance (ft): **.0**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **NO**  
Remarks: **M-707-74**



Code: **MWL**  
Description: **Water Level**

Distance (ft): **.0**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent: **15.000**  
Continuous Index:  
Within 8" of Joint: **NO**  
Remarks:



Code: **CM**  
Description: **Crack Multiple**

Distance (ft): **8.6**  
Structural Grade: **3**  
O&M Grade: **0**  
Clock Start/From: **11**  
Clock To: **12**  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks:


---



Code: **DSF**  
Description: **Deposits Settled Fine**

Distance (ft): **10.8**  
Structural Grade: **0**  
O&M Grade: **3**  
Clock Start/From: **4**  
Clock To: **8**  
1st Value:  
2nd Value:  
Value Percent: **15.000**  
Continuous Index: **S01**  
Within 8" of Joint: **YES**  
Remarks:

---



Code: **DSF**  
Description: **Deposits Settled Fine**

Distance (ft): **19.8**  
Structural Grade: **0**  
O&M Grade: **3**  
Clock Start/From: **4**  
Clock To: **8**  
1st Value:  
2nd Value:  
Value Percent: **15.000**  
Continuous Index: **F01**  
Within 8" of Joint: **NO**  
Remarks:

---



Code: **FH2**  
Description: **Fracture Longitudinal Hinge, 2**

Distance (ft): **19.8**  
Structural Grade: **4**  
O&M Grade: **0**  
Clock Start/From: **12**  
Clock To: **6**  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index: **S02**  
Within 8" of Joint: **YES**  
Remarks:

---



Code: **FH2**  
Description: **Fracture Longitudinal Hinge, 2**

Distance (ft): **23.6**  
Structural Grade: **4**  
O&M Grade: **0**  
Clock Start/From: **12**  
Clock To: **6**  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index: **F02**  
Within 8" of Joint: **NO**  
Remarks:

---



Code: **CL**  
Description: **Crack Longitudinal**

Distance (ft): **23.6**  
Structural Grade: **2**  
O&M Grade: **0**  
Clock Start/From: **12**  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks:


---



Code: **MMC**  
Description: **Material Change**

Distance (ft): **44.7**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **NO**  
Remarks: **pvc**

---



Code:	<b>AMH</b>
Description:	<b>Manhole</b>
Distance (ft):	<b>50.0</b>
Structural Grade:	<b>0</b>
O&M Grade:	<b>0</b>
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	<b>NO</b>
Remarks:	<b>M-706-10.6</b>