Profile/Photo Observation Report



Date: 04/09/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 283.5 Owner: NA Pre Clean: **Not Known** P.O.#: Jen Costello PSR: P-707-021-080 Surveyor:

Customer: Clean Date: 01/01/1900 Shape: C

Street: LINCOLN ST & E 13TH ST Flow Control: Not Controlled

City: Hobart, IN Year Renewed: Location: Light Highway Tape/Media #:

Purpose: Maintenance Related Dia/Height: 8"
Use: Sanitary Material: PVC

Drain Area: NA Lining: Cured in Place

Category: NA

Comment: Reverse setup. roots at 11'-flow incorrect.

Location Details: Direction of Survey: Upstream

US MH: M-707-080 DS MH: M-707-021 Total Length Surveyed (ft): 12.0

2.43 17.00 O&M Index: O&M Quick: O&M Rating: 3.00 3100 3.00 Structural Quick: Structural Rating: Structural Index: 2.50 20.00 Overall Quick: Overall Rating: Overall Index:

	Position	Code	Observation	Video (sec)	Grade
707-	021				
\bigvee	0.	AMH	Manhole	10	NA
ш	0.	MWL	Water Level	21	NA
	\.0	DAGS(S01)	Deposits Attached Grease	32	M 2
	4.8	CM	Crack Multiple	53	S 3
	6.9	RFJ	Roots Fine Joint	69	M 1
	9.4	TFD	Tap Factory Defective	85	M 2
	9.4	RML	Roots Medium Lateral	96	M 3
	11.0	RMJ	Roots Medium Joint	110	M 3
	11.1	RMB	Roots Medium Barrel	122	M 4
	11.1	DAGS(F01)	Deposits Attached Grease	133	M 2
	12.0	MSA	Abandoned Survey	147	NA

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-707-021

 AMH



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 1

Continuous Index:

Within 8" of Joint:

Remarks:

10.000

NO

Code: DAGS

Description: Deposits Attached Grease

Distance (ft): .0
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 4
1st Value:
2nd Value:

Value Percent: 5.000
Continuous Index: S01
Within 8" of Joint: NO

Remarks:



Code: CM


Description: **Crack Multiple**

Distance (ft): 4.8 Structural Grade: 3 0 O&M Grade: Clock Start/From: 1 Clock To: 2 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES




RFJ Code:

Description: **Roots Fine Joint**

Distance (ft): 6.9 Structural Grade: 0 O&M Grade: 1 Clock Start/From: 8 Clock To: 4 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TFD**

Description: Tap Factory Defective

Distance (ft): 9.4
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 3

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks: rml



Code: RML

Description: Roots Medium Lateral


Distance (ft): 9.4
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 2
Clock To: 4
1st Value:
2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: RMJ

Description: Roots Medium Joint

Distance (ft): 11.0
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 8
Clock To: 9
1st Value:

2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

Remarks:

YES

40.000



Code: RMB

Description: Roots Medium Barrel

Distance (ft): 11.1
Structural Grade: 0
O&M Grade: 4
Clock Start/From: 6
Clock To: 12
1st Value:

Value Percent:

Continuous Index:

Within 8" of Joint: NO

Remarks:

2nd Value:



Code: DAGS

Description: Deposits Attached Grease

Distance (ft): 11.1
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 4
1st Value:

1st Value: 2nd Value:

Value Percent: 5.000
Continuous Index: F01
Within 8" of Joint: NO

Remarks:



Code: MSA

Description: Abandoned Survey

Distance (ft): 12.0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO Remarks: roots