Profile/Photo Observation Report



Date: 10/11/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 321.7 Owner: NA Pre Clean: **Not Known** P.O.#: PSR: P-708-007-008 Surveyor: Selasie Honu

Customer: Clean Date: 01/01/1900 Shape: C

Street: 16th. St. Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Light Highway Tape/Media #:

Purpose: Routine Assessment Dia/Height: 12"
Use: Sanitary Material: PVC

Drain Area: **NA** Lining:

Category: NA

Comment:

Location Details: Direction of Survey:


US MH: M-708-008 DS MH: M-708-007 Total Length Surveyed (ft): 319.8

3C21 2.96 71.00 O&M Index: O&M Quick: O&M Rating: 2.00 2C00 46.00 Structural Quick: Structural Rating: Structural Index: **3C2C** 2.49 117.00 Overall Quick: Overall Rating: Overall Index:

Upstream


	Position	Code	Observation	Video (sec)	Grade
708	007				
\bigvee	0.	AMH	Manhole	10	NA
ш	0.	MWL	Water Level	21	NA
П	\\ <u>6.6</u>	TFD	Tap Factory Defective	46	M 2
ш	26.7	TFA	Tap Factory Active	97	NA
	55.1	TF	Tap Factory	165	NA
ш	63.7	TF	Tap Factory	194	NA
Ш	88.2	MWLS(S01)	Water Level Sag	255	S 2
ш	203.3	MWLS(F01)	Water Level Sag	497	S 2
ш	205.9	TF	Tap Factory	514	NA
ш	257.9	TF	Tap Factory	630	NA
ш	264.9	TF	Tap Factory	655	NA
ш	319.8	AMH	Manhole	777	NA

Code:



Description:	Manhole		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Continuous Index:			
Within 8" of Joint:	NO		
Remarks:	M-708-007		

AMH



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:


Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Description: Tap Factory Defective



Distance (ft): 6.6
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 3

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks: root infiltration



Code: TFA

Description: Tap Factory Active

Distance (ft): 26.7
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 1

Clock To:

1st Value: **3.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**

Description: Tap Factory

Distance (ft): 55.1
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 9

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: **TF**

Description: Tap Factory

Distance (ft): 63.7
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: MWLS

Description: Water Level Sag

Distance (ft): 88.2
Structural Grade: 2
O&M Grade: 3

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000
Continuous Index: S01
Within 8" of Joint: NO



Code: MWLS

Description: Water Level Sag

Distance (ft): 203.3
Structural Grade: 2
O&M Grade: 3

Clock Start/From:


Clock To: 1st Value: 2nd Value:

Value Percent: 10.000
Continuous Index: F01
Within 8" of Joint: NO

Remarks:

Code: **TF**

Description: Tap Factory



Distance (ft): 205.9
Structural Grade: 0

O&M Grade: 0
Clock Start/From: 3

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: **TF**

Description: Tap Factory


Distance (ft): 257.9
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 9

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**


Description: Tap Factory

Distance (ft): 264.9
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: AMH
Description: Manhole

Distance (ft): 319.8
Structural Grade: 0

O&M Grade: 0

Clock Start/From: Clock To:

1st Value: 2nd Value: Value Percent:

Continuous Index:

Within 8" of Joint: NO

Remarks: M-708-008