Profile/Photo Observation Report



Date: 04/06/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 82.6 Owner: NA Pre Clean: **Not Known** P.O.#: P-708-021-022 Jen Costello PSR: Surveyor:

Customer: Clean Date: 01/01/1900 Shape: C

Street: Hobart Flow Control: Not Controlled

City: Hobart, IN Year Renewed: Location: Light Highway Tape/Media #:

Purpose: Maintenance Related Dia/Height: 8"
Use: Sanitary Material: PVC

Drain Area: NA Lining: Cured in Place

Category: NA

Comment: Debris at 47'.

Location Details: Direction of Survey: Downstream

US MH: M-708-021 DS MH: M-708-022 Total Length Surveyed (ft): 48.8

2.00 2A00 20.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 2.00 2A00 20.00 Overall Index: Overall Quick: Overall Rating:

Code:



| L |
|---|
| |

AMH



Code: MWL Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

20.000

NO




Code: DAGS

Description: **Deposits Attached Grease**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 2 Clock Start/From: 8 Clock To: 4 1st Value: 2nd Value:

Value Percent: 5.000 Continuous Index: **S01** Within 8" of Joint: NO

Remarks:



Code: MWL

Description: Water Level

Distance (ft): 29.6
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: MSA

Description: Abandoned Survey

Distance (ft): 48.8
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: **OVERTURNED**



Code: DAGS

Description: Deposits Attached Grease

Distance (ft): 48.8
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 8

Clock To: 4

1st Value:

1st Value: 2nd Value:

Value Percent: 5.000
Continuous Index: F01
Within 8" of Joint: NO

Remarks: