
Profile/Ph	oto Observatio	n Report			RedZone
Date:	04/06/2018	Weather:		Coding:	PACP 6.0
Pipe Length (ft)	: <b>82.0</b>	Owner:	NA	Pre Clean:	Not Known
P.O.#:		Surveyor:	Jen Costello	PSR:	P-708-021-022
Customer:		Clean Date:	01/01/1900	Shape:	С
Street:	OFF S LAKE PARK	AVE	Flow Control:	Not Controlled	
City:	Hobart, IN		Year Renewed:		
Location:	Parking Lot		Tape/Media #:		
Purpose:	Maintenance Rela	ated	Dia/Height:	8"	
Use:	Sanitary		Material:	PVC	
Drain Area:	NA		Lining:	Cured in Place	
Category:	NA				
Comment:	Reverse setup. D	ebris at 28'.			
Location Details	s:		Direction of Surv	vey: Upstream	
US MH:	M-708-021	DS MH:	M-708-022	Total Length Surveyed (ft)	: <b>30.0</b>
0&M Index:	2.00	O&M Quick:	230	0 O&M Rating:	6.00
tructural Index:	0.00	Structural Qu	uick: 000		0.00
Overall Index:	2.00	Overall Quic	k: 230	<b>0</b> Overall Rating:	6.00





Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-708-022



Code: MWL Description: Water Level

Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code:	DAGS
Description:	<b>Deposits Attached Grease</b>

Distance (ft):	.0
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	7
Clock To:	5
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	S01
Within 8" of Joint:	NO
Remarks:	



Code:DAGSDescription:Deposits Attached Grease

Distance (ft):	15.9
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	7
Clock To:	5
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	F01
Within 8" of Joint:	NO
Remarks:	



Code:	MWL
Description:	Water Level
Distance (ft):	15.9

Distance (ft):	15.9
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	30.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code: Description: MSA Abandoned Survey

Distance (ft):	30.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	overturned