Profile/Photo Observation Report



Date: 10/11/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 396.8 Owner: NA Pre Clean: **Not Known** P.O.#: PSR: P-708-103-102 Surveyor: Selasie Honu

Customer: Clean Date: 01/01/1900 Shape: C

Street: BRACKEN PKWY Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Light Highway Tape/Media #:

Purpose: Routine Assessment Dia/Height: 12"
Use: Sanitary Material: VCP

Drain Area: **NA** Lining:

Category: NA

Comment:


Location Details: Direction of Survey: **Downstream**

US MH: M-708-103 DS MH: M-708-102 Total Length Surveyed (ft): 406.7

3100 3.00 3.00 O&M Index: O&M Quick: O&M Rating: 2.00 2100 2.00 Structural Quick: Structural Rating: Structural Index: 2.50 3121 5.00 Overall Quick: Overall Rating: Overall Index:


	Position	Code	Observation	Video (sec)	Grade
1(708-)1	03				
	.0	AMH	Manhole	10	NA
	\0	MWL	Water Level	21	NA
	403.2	MWLS	Water Level Sag	839	S 2
	406.7	AMH	Manhole	857	NA
ш					
ı					
l					
l					
l					

Code:



Manhole
.0
0
U
NO
M-708-103

AMH



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

5.000

NO

Code: **MWLS**

Description: **Water Level Sag**



Distance (ft): 403.2 2

Structural Grade: O&M Grade: 3

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: AMH
Description: Manhole

Distance (ft): 406.7
Structural Grade: 0

O&M Grade: 0

Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index: Within 8" of Joint:

Remarks: M-708-102

NO