
Profile/Ph	oto Observatio	n Report			RedZon
Date:	04/04/2018	Weather:		Coding:	PACP 6.0
Pipe Length (ft): 150.7	Owner:	NA	Pre Clean:	Not Known
P.O.#:		Surveyor:	Jen Costello	PSR:	P-708-104-103
Customer:		Clean Date:	01/01/1900	Shape:	С
Street:	BRACKEN PKWY		Flow Control:	Not Controll	ed
City:	Hobart, IN		Year Renewed:		
Location:	Sidewalk		Tape/Media #:		
Purpose:	Maintenance Rela	ated	Dia/Height:	12"	
Use:	Sanitary		Material:	PVC	
Drain Area:	NA		Lining:	Cured in Pla	ce
Category:	NA				
Comment:	Debris at 41'.				
Location Detail	ls:		Direction of Su	rvey: Downstream	า
US MH:	M-708-104	DS MH:	M-708-103	Total Length Surveyed	(ft): 42.8
D&M Index:	2.00	O&M Quick:	29	00 O&M Rating:	18.00
Structural Index:	0.00	Structural Q	uick: 00	00 Structural Ratir	ng: 0.00
Overall Index:	2.00	Overall Quic	k: 29	00 Overall Rating:	18.00





Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-708-104



Code: MWL Description: Water Level

Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	30.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code:	DAGS
Description:	Deposits Attached Grease

Distance (ft):	.0
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	S01
Within 8" of Joint:	NO
Remarks:	




Code: I Description:

MSA Abandoned Survey

Distance (ft):	42.8
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	OVERTURNED

Code: Description: DAGS Deposits Attached Grease



Distance (ft):	42.8
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	F01
Within 8" of Joint:	NO
Remarks:	