## **Profile/Photo Observation Report**



Date: 04/04/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 396.3 Owner: NA Pre Clean: **Not Known** P.O.#: Jen Costello PSR: P-708-106-105 Surveyor:

Customer: Clean Date: 01/01/1900 Shape: C

Street: BRACKEN PKWY & LAKE ST Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Sidewalk Tape/Media #:

Purpose: Maintenance Related Dia/Height: 12"
Use: Sanitary Material: PVC

Drain Area: NA Lining: Cured in Place

Category: NA
Comment: Reverse setup. Debris at 12'.


Location Details: Direction of Survey: Upstream

US MH: M-708-106 DS MH: M-708-105 Total Length Surveyed (ft): 13.8

0000 0.00 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 0.00 0000 0.00 Overall Rating: Overall Index: Overall Quick:


Position	Code	Observation	Video (sec)	Grade
708-105				
.0	AMH	Manhole	10	NA
0.	MWL	Water Level	22	NA
13.8	MSA	Abandoned Survey	61	NA

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-708-105

AMH



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

Code:

Description:

40.000

NO

MSA

13.8

0

0

**Abandoned Survey** 



O&M Grade:
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: UNDER WATER